

15-135-19072-00-00

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner M. B. Armer Address 711 Petroleum Bldg., Wichita, Kansas
(Applicant)

Lease (Farm Name) Frevele A Well No. 1

Well Location NWSENE $\frac{1}{4}$ (3630 ft. N of S line Sec. 27 Twp. 16 Rge. 25 (E) (W) and 4290 ft. E of W line.)

County Ness Field Name (if any) _____

Total Depth 4553 Oil ___ Gas ___ Dry Hole ___ Dry Hole

Was well log filed with application? No If not, explain: _____

Filing with Well Plugging Record

Date and hour plugging is desired to begin November 16, 1957

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

C. O. Moore Address Great Bend, Kansas

Plugging Contractor H-30, Inc.

Plugging Contractor's Licence No. _____

Address 709 Petroleum Bldg., Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____

M. B. Armer Address 711 Petroleum Bldg., Wichita, Kansas

and payment will be guaranteed by applicant.

PLUGGING
NOV 27 16 1957
BOOK PAGE 0211 of 3

[Signature]
Applicant or Acting Agent

Date 11/20/57

RECEIVED
STATE CORPORATION COMMISSION
NOV 21 1957
CONSERVATION DIVISION
Wichita, Kansas

15-135-19072-00-00

STATE OF KANSAS
State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas
November 18, 1957


Well No.	1
Lease	Fracle "A"
Description	NW 3/4 Sec 27-16-25W
County	Jess
File No.	62-3

M. B. Armer
711 Petroleum Building
Wichita, Kansas

Dear Sir:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. N. A. Rives, Box 8, Pratt, Kansas Ph. 11 36

Very truly yours,


Jewel M. Ogden
Director of Conservation Division

cc:
District Plugging Supervisor