KCC OIL/GAS REGULATORY OFFICE

DATE 12/2/97	[] New Situation	
OPERATOR Ranken Energy Corp. # 3447	[] Response to Request [] Follow-up	
NAME 601 N. Kelly, Ste. 103	_ LOCATION NE SE NW ,SEC 23 ,T 16 S,R 29 EX	
& ADDRESS Edmond, OK 73003-4855	LEASE Dowell Well #	
PHONE NO. OPER. 316-653-7368 OTHER	COUNTY Lane API#15-101-21,744 0000	
REASON FOR INVESTIGATION: Alternate II ceme	nt completion	
	EASE INSPECTION	
PROBLEM:		
	<u>_</u>	
PERSON(S) CONTACTED:	•	
- EROON(3) CONTACTED.		
FINDINGS: Surface pipe set at 210', 5½" at	4615' w/175 sx cement, TD at 4615'	
Port collar at 2202 cemented with 400 sx 60/	40 Pozmix 8% gel ¼# floseal. Cement did	
circulate.	COMPLAINT	
• •	<u>6</u>	
ACTION/RECOMMENDATIONS: The Alternate II	photos taken:	
	<u> </u>	
	T X	
Retain 1 copy Joint District Office	By Michael Maier	
Send 1 copy Conservation Division	12/2/97	