	4/20/94	ALTZ
DATE:	4/20/94	[] New Situation [] Response to Request [] Follow-Up
	LOCA	ATION NE NE NE, SEC 1, T 19 S, R 28W
OPERATOR:	Ritchie Exploration, Inc.	LICENSE #: 4767
ADDRESS:	125 N. Market, Ste. 1000	TRACE/WELL NUMBER. Buerkle Farm
ADDRESS:	Wichita, KS 67202	#1
PHONE #:	316-267-4375	COUNTY: Lane API#15-101-21,674
LEA	SE INSPECTION:	COMPLAINT: FIELD REPORT: X
REASON FO	R INVESTIGATION: Alterna	te II cementing
PROBLEM:		
PERSONS CO		
FINDINGS:		ied were on location. The port collar at 2055, was
		以# floseal were pumped in. Six barrels of cement
	ited to the pit.	
The job bega	an at 12:15 p.m. and was comple	ete at 12:45 p.m.
		PHOTOS TAKEN:
ACTION/REG	COMMENDATIONS: Job complete	
		- WKC1
		CUNSERVATION DIVISION Wichita, Kansas
		Mione
		dis
·		BYSteve Middleton

4/20/94

-LEASE INSPECTION

YE3	NONE COMMENTS	
[] I.D. Sign	[]	
[] Tank Battery:	[]; Condition: good [] questionable [] overflowin	9[]
[] Pits, tank battery	[]; Fluid depthft.; approx. sizeft x	
[] Pit, injection site	[]; Fluid depthft.; approx. sizeft x	
[,] Gas venting		_
[] Oil spill evidence		
[] Saltwater evidence	[]; Surface flow; seepage	
[] Saltwater pipelines	[]; Seepage visible Yes/No; tested for leaks Yes/No	
[] Flowing holes	[]	
[] Abandoned wells	(,)	
[] TA wells	[]; Potential poll. prob; currently producing	
[] SWD/ER Injection well [] SWD/ER Injection well [] SWD/ER Injection well [] SWD/ER Injection well	[]; Permit # Pressure-actual psi,Authorize	dpsi dpsi
[] Monitoring records	[]	
[] Gauge connections [] Gauge connections	[]: tubing; T/C annulus; C/SP annulu; C/SP annul	s
Water samples taken	odsatisfactorypoorvery bad	
Reports prepared		+ -
		+
		+ -
		+
		+ -
-		
		+ -