

KCC OIL/GAS REGULATORY OFFICE

ALT 2

DATE 9/22/93

- New Situation
- Response to Request
- Follow-up

OPERATOR Bankoff Oil Company # 6040


NAME 155 N. Market, Ste. 1050 A

& ADDRESS Wichita, KS 67202

LOCATION 50' E of SW SW SW, SEC 7, T 16 S, R 21 W

LEASE Bisagno Well # 1

PHONE NO. OPER. _____ OTHER _____

COUNTY Ness API # 15-135-23,762 

REASON FOR INVESTIGATION: Witness Alternate II cementing

LEASE INSPECTION

PROBLEM: _____

PERSON(S) CONTACTED: Eldon Reed

FINDINGS: Port collar set at 1653'. Pulled rods and tubing, ran tubing back to 1653',

opened port collar and pumped 250 sx 60/40 Pozmix 6% gel, cement did circulate.

A 20 barrel gel slurry was pumped ahead of the cement.

COMPLAINT

RECEIVED
STATE CORPORATION COMMISSION
SEP 29 1993
CONSERVATION DIVISION
Wichita, Kansas

photos taken: _____

ACTION/RECOMMENDATIONS: _____

FIELD REPORT



Retain 1 copy Joint District Office
Send 1 copy Conservation Division

By Duane Rankin

9/24/93

