MANSAS

Form CP-3 Rev. 6-4-68

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

RECEIVED STATE CORPORATION COMMISSION

J. Lewis Brock
Administrator
P. O. Box 17027
Wichita, Kansas 67217

APR 8 - 1974

CONSERVATION DIVISION Wichita, Kansas

Lease Name	Complete	Address	Box 287, 1	meat diendank	ansas 6752	30		
Location 1900 FML 2 600 FSL of SW/4 Sec. 4 Twp. 17 Rge. (E) (County Ness Total Depth 4510° Abandoned Oil Well Gas Well Input Well SWD Well D & A Other well as hereafter indicated Plugging Contractor Slawson Drlg. Address Wichita, Kansas License No. Operation Completed: Hour 11:40 P Day 4 Month 4 Year 1974 The above well was plugged as follows: RTD 4510° 8 5/8 csg set at 307° cwc. Gunned pits, circulated heavy mud, set 75 sk cem. plug (4502°-4302°) Filled hole with heavy mud-to 1180° -set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357° -set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. Signed: Well Plugging Superviors		e	МоЗ	llenkamp	Wel	1 No. 1 -	AB	
Abandoned Oil Well Gas Well Input Well SWD Well D&A Other well as hereafter indicated Plugging Contractor Slawson Drlg. Address Wichita, Kansas License No. Operation Completed: Hour 11:40 P Day 4 Month 4 Year 1974 The above well was plugged as follows: RTD 4510° 8 5/8 csg set at 307° cwc. Gunned pits, circulated heavy mud, set 75 sk cem. plug (4502°-4302°) Filled hole with heavy mud-to 1180° -set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357° -set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. Signed: Signed: Well Plugging Supervisor	Location_	1980' FWL 8	660° FSL of	SW/4	Sec4	Twp. 17 Rg	e(E)	(W)
Other well as hereafter indicated Plugging Contractor Slawson Drlg. Address Wichita, Kansas License No. Operation Completed: Hour 11:40 P Day 4 Month 4 Year 1974 The above well was plugged as follows: RTD 4510° 8 5/8 csg set at 307° cwc. Gunned pits, circulated heavy mud, set 75 sk cem. plug (4502°-4302°) Filled hole with heavy mud-to 1180° -set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357° -set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. Signed: Signed: Supervisor Well Plugging Supervisor	County		Ness			Total Depth	4510	
Plugging Contractor Wichita, Kansas Dicense No. Deparation Completed: Hour 11:40 P Day 4 Month 4 Year 1974 The above well was plugged as follows: RTD 4510° 8 5/8 csg set at 307° cwc. Gunned pits, circulated heavy mud, set 75 sk cem. plug (4502°-4302°) Filled hole with heavy mud-to 1180° -set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357° -set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. Signed: Heavy Mud to 40° Supervisor. Well Plugging Supervisor.	Abandoned	Oil Well	Gas Wel	1Inp	ıt Well	SWD Well	1D &	A X
Wichita, Kansas Dicense No. Operation Completed: Hour 11:40 P Day 4 Month 4 Year 1974 The above well was plugged as follows: RTD 4510° 8 5/8 csg set at 307° cwc. Gunned pits, circulated heavy mud, set 75 sk cem. plug (4502°-4302°) Filled hole with heavy mud-to 1180° -set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357° -set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. Signed: Signed: Supervisor	Other well	l as hereafte	r indicated_					
Operation Completed: Hour 11:40 P Day 4 Month 4 Year 1974 The above well was plugged as follows: RTD 4510° 8 5/8 csg set at 307° cwc. Gunned pits, circulated heavy mud, set 75 sk cem. plug (4502°-4302°) Filled hole with heavy mud-to 1180° -set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357° -set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. Signed: Filled hole with the above well was plugged as herein stated.	Plugging (Contractor		Slawson	Drlg.			
Operation Completed: Hour 11:40 P Day 4 Month 4 Year 1974 The above well was plugged as follows: RTD 4510° 8 5/8 csg set at 307° cwc. Gunned pits, circulated heavy mud, set 75 sk cem. plug (4502°-4302°) Filled hole with heavy mud-to 1180°-set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357°-set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. Signed: Filled hole with the above well was plugged as herein stated.	Address		Wichita	, Kansas	7	License No	0.	
The above well was plugged as follows: RTD 4510° 8 5/8 csg set at 307° cwc. Gunned pits, circulated heavy mud, set 75 sk cem. plug (4502°-4302°) Filled hole with heavy mud to 1180° -set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357° -set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. Signed: Signed: Well Plugging Supervisor	Operation	Completed:	Hour_11:40	P Day 4				******
Gunned pits, circulated heavy mud, set 75 sk cem. plug (4502°-4302°) Filled hole with heavy mud-to 1180°-set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357°-set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. Signed: Signed: Well Plugging Supervisor	The above	well was plu	gged as follo	ows:				
Filled hole with heavy mud-to 1180° -set 50 sk cem. plug (1180°-1030°) Filled hole with heavy mud to 357° -set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. The base of cellar is the above well was plugged as herein stated. Signed: Signed: Well Plugging Supervisor			•					
Filled hole with heavy mud to 357° -set 50 sk cem. plug (357°-257°) Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cem to base of cellar. The hereby certify that the above well was plugged as herein stated. Signed: Well Plugging Supervisor	Gunned pi	ts, circulat	ed heavy mud	, set 75 sk	em. plug	(4502*-4302	·)	
Filled hole with heavy mud to 40° set cementing plug, 1/4 sk hulls and 10 sk cement to base of cellar. Thereby certify that the above well was plugged as herein stated. Signed:	Filled ho	le with heav	y_mud-to 118	0• =set 50 sl	cem. plu	g (1180'-10	301)	
to base of cellar. hereby certify that the above well was plugged as herein stated. Signed: Signed: Well Plugging Supervisor	Filled ho	le with heav	y mud to 357	-set 50 sk	cem. plug	(357*-257*)	
hereby certify that the above well was plugged as herein stated. Signed: Signed: Well Plugging Supervisor	Filled ho	le with heav	y mud to 40°	set cementin	ng plug, l	/4 sk hulls	and 10 sk	com.
Signed: Well Plugging Supervisor	to base o	f cellar.						
Signed: Well Plugging Supervisor								· ***********
Signed: Well Plugging Supervisor					· · · · · · · · · · · · · · · · · · ·			
Well Plugging Supervisor	hereby c	ertify that	the above wel	l was plugge	d as herei	n stated.		···
Well Plugging Supervisor						φ,	W -	
W					Signed:	- n . n	* V* -	