

ALT2

15-135-23237-0001

KCC OIL/GAS REGULATORY OFFICE

DATE 5/10/89

- New Situation
- Response to Request
- Follow-up

OPERATOR G.A.B.S. 011 #30083

NAME

LOCATION C W/2 SW SEC 20, T 17 S, R 21 W

ADDRESS

LEASE Brenner Well # 1 OWWO

PHONE NO. OPER. OTHER

COUNTY Ness

REASON FOR INVESTIGATION: Alternate II cement squeeze

LEASE INSPECTION

PROBLEM:

PERSON(S) CONTACTED: Dean Ives

FINDINGS: Perforated 4 1/2" casing at 1400' (Anhydrite top 1520') squeezed perfs with 275 sx 60/40 Pozmix 6% gel, 1/4" floseal. Cement circulated to surface.

RECEIVED
 CORPORATION COMMISSION
 MAY 15 1989
 CONSERVATION DIVISION
 Wichita, Kansas

COMPLAINT

ACTION/RECOMMENDATIONS: None. photos taken:

FIELD REPORT X

Retain 1 copy Joint District Office
Send 1 copy Conservation Division

By Dan Goodrow
5/10/89