## DISTRICT CONSERVATION AGENT'S REPORT

				<u> </u>
State Corporatio	on Commission			
Conservation Div 211 North Broadw				FILE NO.
Wichita, Kansas	v			<del></del>
		÷		LOCATION NW NW
				SEC. 31 TWP. 11 RGE.
Dry Hole x	Abandoned Oil	WellAban	doned Gas	Well
	completed superv			i i j
	Lease		c	
CEL D	orado Refg Co		Fl_Don	ado, Kans
operator		Address		······································
Field	<del></del>	County_	ETTIS	
Total Depth	3785 Fee	t.		
	torBrack Dr			•
tragging concrac	tor	G - 0		
Plugging Contrac	tor's License No.	<del></del>		
Address				
(:	Describe briefly			ell was plugged)
(:	Describe briefly			ell was plugged)
8 5/8" at 2	69' circulated	with cement.	,	
8 5/8" at 2	69' circulated hole with heav	with cement. y mud, set ce	men ting	plug at 250', 1/2
8 5/8" at 2 Circulated sack hulls	69' circulated hole with heav and 15 sax cem	with cement. y mud, set ce ent, mud to 4	menting	plug at 250', 1/2
8 5/8" at 2 Circulated sack hulls	69' circulated hole with heav	with cement. y mud, set ce ent, mud to 4	menting	plug at 250', 1/2
8 5/8" at 2 Circulated sack hulls	69' circulated hole with heav and 15 sax cem	with cement. y mud, set ce ent, mud to 4	menting	plug at 250', 1/2
8 5/8" at 2 Circulated sack hulls	69' circulated hole with heav and 15 sax cem	with cement. y mud, set ce ent, mud to 4	menting	plug at 250', 1/2
8 5/8" at 2 Circulated sack hulls	69' circulated hole with heav and 15 sax cem	with cement. y mud, set ce ent, mud to 4	menting	plug at 250', 1/2
8 5/8" at 2 Circulated sack hulls	69' circulated hole with heav and 15 sax cem	with cement. y mud, set ce ent, mud to 4	menting	plug at 250', 1/2
8 5/8" at 2 Circulated sack hulls	hole with heav and 15 sax cem	with cement.  y mud, set ce ent, mud to 4 cement to be	menting	plug at 250', 1/2
8 5/8" at 2 Circulated sack hulls	hole with heav and 15 sax cem	with cement.  y mud, set ce ent, mud to 4 cement to be	omenting O', set	plug at 250', 1/2 cementing plug, lar.
8 5/8" at 2 Circulated sack hulls	69' circulated hole with heav and 15 sax cem	with cement.  y mud, set cement, mud to 4  cement to bo	menting O', set ttom cel	plug at 250', 1/2