

KCC OIL/GAS REGULATORY OFFICE

Date 8-16-01

15-135-24148-0000

Att. Jim Ho

- New Situation
- Response to Request
- Follow-up

ALTZ

Operator Palmino Petro. Inc. #

20'w of

1980 FWL
1250 FWL

Address _____

Location E-S $\frac{1}{2}$ -NW, Sec 21, T 17S, R 24W

Lease Habiger-Keilman Well # 6

Phone No. _____

County Ness

Oper. _____ Other _____

Reason for Investigation: AIT # Competition Log TD 4369'

Problem: _____

Person(s) Contacted: _____

Findings: Pickell Dc/s can tubing in hole open port collar @ 1630'

Swift Service pumped 135sx of SMD cement w/ $\frac{1}{4}$ " # Flow seal
circulated to surface. shut port collar & pressured up to 1000 #

photos taken: _____

Action/Recommendations: Starting Time 2:30 pm

Completion Time 3:30

RECEIVED

AUG 21 2001

KCC WICHITA

By Kevin D Strube

PIAT II

- Lease Inspection
- Complaint
- Field Report

Retain 1 copy Joint District Office
Send one copy Conservation Division