

DATE: 3/11/94

LSINS

[] New Situation
[X] Response to Request
[] Follow-Up

15-135-23801-00-00

LOCATION NE, SEC 30, T 19 S, R 21W

OPERATOR: American Warrior

LICENSE #: _____

ADDRESS: _____

LEASE/WELL NUMBER: Moore #3-30

ADDRESS: _____

COUNTY: Ness

PHONE #: _____

LEASE INSPECTION: _____ COMPLAINT: X FIELD REPORT: X

REASON FOR INVESTIGATION: Request by Dave Williams

PROBLEM: _____

PERSONS CONTACTED: Scott Corsair with American Warrior

FINDINGS: 3/8/94 Arrived on location at 4:30 p.m. Tagged bottom with logging tool at 4414'. Perforated well at 4397-4400'.

Company planned to perforate Ft. Scott at 4336' to 4342' if lower zone was not commercial.

3/10/94 Scott Corsair called and said Conglomerate perms were productive. Ft. Scott will not be perforated until later.

PHOTOS TAKEN: _____

ACTION/RECOMMENDATIONS: _____

RECEIVED
STATE CORPORATION COMMISSION
MAR 14 1994
3-14-94
CONSERVATION DIVISION
Wichita, Kansas

BY Steve Durrant
3/11/94