

KCC OIL/GAS REGULATORY OFFICE

DATE: 2/15/94

LSINS
15-135-23799-00-00

[] New Situation
[X] Response to Request
[] Follow-Up

LOCATION _____, SEC 30, T 19 S, R 21W

OPERATOR: American Warrior Inc.

LICENSE #: 4058

ADDRESS: P.O. Box 399

LEASE/WELL NUMBER: Moore #1-30

ADDRESS: Garden City, KS 67846-0399

COUNTY: Ness

PHONE #: 316-275-9231

LEASE INSPECTION: _____	COMPLAINT: _____	FIELD REPORT: <u> X </u>
-------------------------	------------------	----------------------------

REASON FOR INVESTIGATION: Request by district supervisor

PROBLEM: _____

PERSONS CONTACTED: Scott Corsair

FINDINGS: On 2/15/94, I observed that the above well was perforated from 4327-4330'.

Mr. Corsair informed me that the total depth of the well was 4421' and that 5½" casing had been set at 4416', with a formation packer set at 4416'. Additionally there was 6 or 7' of cement left from 4410' to the bottom of the 5½" casing..

The well was logged prior to perforating-copy enclosed with this report. The well was not logged prior to setting the 5½" casing.

PHOTOS TAKEN: _____

ACTION/RECOMMENDATIONS: _____

RECEIVED
STATE CORPORATION COMMISSION

FEB 21 1994
2-21-94

CONSERVATION DIVISION
Wichita, Kansas

BY Duane Rankin
2/15/94