

KCC OIL/GAS REGULATORY OFFICE

DATE 2/29/96

New Situation
 Response to Request
 Follow-up

OPERATOR Ritchie Exploration, Inc. # 4767

NAME 125 N. Market, Ste. 1000

LOCATION NE/4, SEC 31, T 19 S, R 21 W

& ADDRESS Wichita, KS 67202

LEASE Lyle Schaben "P" Well # 2

PHONE NO. _____
OPER. 316-267-4375 OTHER _____

COUNTY Ness

API# 15-135-23,925-00-00

REASON FOR INVESTIGATION: Alternate II cementing had not been done.

LEASE INSPECTION

PROBLEM: _____

PERSON(S) CONTACTED: Bennie Dills, Production Superintendent

FINDINGS: 5 1/2" at 4494', Baker port collar at 1462', 8 5/8" at 323', TD 4500'

Allied pumped 185 sx 65/35 Pozmix 6% gel 1/4# floseal. Circulated cement to surface.
On location at 10 a.m., finished at 12 p.m.

COMPLAINT

RECEIVED
KANSAS CORP COMM
1996 MAR -7 A M 24
3-7-96

photos taken: _____

ACTION/RECOMMENDATIONS: Alternate II cementing completed.

FIELD REPORT

By Kevin Strube

2/29/96

Retain 1 copy Joint District Office
Send 1 copy Conservation Division