## KCC OIL/GAS REGULATORY OFFICE

DATE3/3/93	[ ] New Situation	
OPERATOR Mull Drilling Company, Inc. # 5144	[ ] Response to Request _ [ ] Follow-up	
NAME P.O. Box 2758	LOCATION_E/2 E/2 SE, SEC 5 ,T 19 S,R 24	XEX W
ADDnESS Wichita, KS 67201-2758	LEASE Borger Well #	-
PHONE NO. OPER. OTHER	COUNTYNess API #15-135-23,734 -	- - -
REASON FOR INVESTIGATION: <u>Alternate II cemen</u>	nt completion	NOI
	RECEIVED	INSPECTION
PROBLEM:	KANSAS CORPORATION COMMISSION	1
	MAR 2 4 1993	LEASE
PERSON(S) CONTACTED: Jerry Roane	CONSERVATION DIVISION WICHITA, KS	
FINDINGS: DV at 1618, pumped 300 sx cement	. Cement did circulate.	· · ·
		TMI
		COMPLAINT
·		
		_
•		
/5		
ACTION/RECOMMENDATIONS:	photos taken:	REPORT
	ł	
		FIELD
Retain 1 copy Joint District Office Send 1 copy Conservation Division	By Dan Goodrow	_
The state of the s	3/3/93	_ Ø

## LEASE INSPECTION

YES	NONE COMMENTS	•
[ ] I.D. Sign	[]	
[ ] Tank Battery	[ ]; Condition: good [ ] questionable [ ] overflowing	g.[.]
[ ] Pits, tank battery	[ ]; Fluid depthft.; approx. sizeft x	_ft
[ ].Pit, injection site	[ ]; Fluid depthft.; approx. sizeft x	_ft
[ ] Gas venting		
[ ] Oil spill gyidence		
[ ] Saltwater evidence	[ ]; Surface flow; seepage	
[ ] Saltwater pipelines	[ ]; Seepage visible Yes/No; tested for leaks Yes/No	
[ ] Flowing holes		
[ ] Abandoned wells		
[ ] TA wells	[]; Potential poll. prob; currently producing_	<del></del>
		edpsi edpsi
[ ] Monitoring records	[ ]	
	[ ]: tubing; T/C annulus; C/SP annulu	\$S
Lease cleanliness: very go	odsatisfactorypoorvery_bad	
Water samples taken	<del></del>	
Reports prepared		+ -
		+ -
		+++
		+ -
t :		+ -
•		1