12-14 TO: API Number: 15-051-23, 133-000 STATE CORPORATION COMMISSION NW NW NE ____/4 SEC.___**31**__,_**11**__S,_**19**__W CONSERVATION DIVISION - PLUGGING __ feet from S section line 130 SOUTH MARKET, SUITE 2078 4950 feet from E section line WICHITA, KANSAS 67202 2310 Lease: Solomon "B-P" Well # 6. Operator license# 4767 Operator: Ritchie Exploration, Inc. County: Ellis 123,44 Well total depth_____3798 Address: 125 N. Market - Suite #1000 feet Conductor Pipe: 0 inch @ Wichita, Kansas 67202 0 feet Surface pipe 8 5/8 Inch @ 175 feet Aband. oil well_x, Gas well____, Input well___, SWD___, D & A_____ Plugging contractor: Mike's Testing and Salvage, Inc. License# 31529 Address: P.O. Box 209 - Chase, Kansas 67524 Company to plug at: Hour: 3:00 P.M. Day: 14 Month: December Year: 1995 Plugging proposal received from: Mike Kelso Company: Mike's Testing and Salvage, Inc. Phone: 316-938-2943 Were: Order 290 sxs 60/40 posmix - 10% gel and hulls. Plug while pulling casing. Plugging Proposal Received by: ___ Herb Deines_ Plugging operations attended by agent? All[], Part[X], None[Hour: 8:30 P.M., Day: 14, Month: December, Year: 1995 Completed: Actual plugging report: 8 5/8" to 175'. 5 1/2" to 3798' w/250 sxs. Perfs from 3706' -3720'. Sanded to 3650' and spotted 5 sxs cement with dump bailer. Shot casing loose at 2115' and pulled to 2100'. Mixed and pumped 145 sxs cement with 200#. Pulled casing to 1580' and pumped 40 sxs with 100# hulls. Pulled casing to 775' and pumped 40 sxs with 100# hulls. Pulled casing to 225' and circulated cement to surface with 50, sxs cement with 100# hulls. Pulled casing and topped with 20 sxs cement. CTATE CORPORATION TO THE Remarks: Allied Cementing. Anhy.plug: YES X NO Condition of casing(in hole): GOOD X BAD Bottom plug(in place): YES___, CALC___X_, NO__ Dakota plug: YES_X___, NO___ Plugged through TUBING ____, CASING X ___. Elevation:___ $\mathsf{hot}[\ \mathbf{X}\]$ observe the plugging. (agent) Form CP-2/3