STATE OF KANSAS STATE CORPORATION COMMISSION

Atl Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission

WELL PLUGGING RECORD

212 North Market, Insurance Bldg. Wichita, Kansas							18 (E) !! (T
NORTH	Locat	tion as "Nl	E/CNWXSWX"	or footage fr	om lines $ m K$	<u>u nu nu </u>	
		Owner	nbour Obsett	rson "C	operties,	THC.	
		Name	Rings	003 01-	<u>iru</u> lubomo		_ Well No
i		Address_					
i							19
			plugging appro	and			10
i i			enced	3-11-6	0		19
			leted	3-17-6			
				ell or producir			
						,	
	Ifag	producing	well is abandor	ned, date of 1	ast production		19
* - 1 - 1 1	Was	permission	obtained from	n the Conser	vation Division o	r its agents bef	oré plugging was co
Locate well correctly on above Section Plat	menc		yes	dan Dat	L		
ne of Conservation Agent who				don Pet			2526
ducing formation				Botto	m	Total Depth of	Well 3526 F
w depth and thickness of all w	vater, oil and gas	s formation	15.				
DIL, GAS OR WATER REC	ORDS						CASING RECORD
	CONT	ENT	FROM	70			T
FORMATION	GUNT	- Let	FRUM	10	8-5/8"	PUT IN	PULLED DUT
				-	5-1/2"	1248' 3515'	nore_
					1 7 7 7	<u> </u>	nona
		•					
				 -			
						,	
Describe in detail the mann atroducing it into the hole. It feet for each pl	f cement or other ug set. Checker	er plugs we	hole to	the character	of same and depth	it open	fee
ntroducing it into the hole. If	Checker Filled cement	d the W/sar	hole to ad to 320 bailer.	34721 : 00 and Hooker	and found dumped 4 up circus of gel m	it open sacks o	fee
stroducing it into the hole. If	Checkor Filled cement pump a filled	d the W/sar With nd pun to 50	hole to ad to 320 bailer.	34721 : 00 and Hooker	of same and depth and found dumped b	it open sacks o	fce
stroducing it into the hole. If	Checkor Filled cement pump a filled to base	d the Wish and punto 50 e of c	hole to do to 320 bailer. npcd in 2	34721 : 00 and Hooker	and found dumped 4 up circus of gel m	it open sacks o	fee
stroducing it into the hole. If	Checkor Filled cement pump a filled to base	d the Wish and punto 50 e of c	hole to ad to 320 bailer.	34721 : 00 and Hooker	and found dumped 4 up circus of gel m	it open sacks o	fee
stroducing it into the hole. If	Checkor Filled cement pump a filled to base	d the Wish and punto 50 e of c	hole to do to 320 bailer. npcd in 2	34721 : 00 and Hooker	and found dumped 4 up circus of gel m	it open sacks o	fee
stroducing it into the hole. If	Checkor Filled cement pump a filled to base	d the Wish and punto 50 e of c	hole to do to 320 bailer. npcd in 2	34721 : 00 and Hooker	and found dumped 4 up circus of gel m	it open sacks o	fce
stroducing it into the hole. If	Checkor Filled cement pump a filled to base	d the Wish and punto 50 e of c	hole to do to 320 bailer. npcd in 2	34721 : 00 and Hooker	and found dumped 4 up circus of gel m	it open sacks o	fce
ntroducing it into the hole. If	Checkor Filled cement pump a filled to base	d the Wish and punto 50 e of c	hole to do to 320 bailer. npcd in 2	34721 : 00 and Hooker	and found dumped 4 up circus of gel m	it open sacks o	fce
ntroducing it into the hole. If	Checkor Filled cement pump a filled to base	d the Wish and punto 50 e of c	hole to do to 320 bailer. npcd in 2	34721 : 00 and Hooker	and found dumped 4 up circus of gel m	it open sacks o	fee
ntroducing it into the hole. If	Checkor Filled cement pump a filled to base	d the W/Sar With nd pun to 50 e of c	hole to ad to 320 bailer. aped in 2 00'. Pi cellar.	34721 : 2001 and Hooker 23 sacks amped in	of same and depth and found dumped 4 lup circu a of gel n a 54 sacks	it open sacks o	fee
ntroducing it into the hole. It feet for each pl	Checker Filled cement pump a filled to base	d the W/sar With nd pun to 50 e of c	hole to do to 320 bailer. ped in 2 00'. Pr cellar.	34721 : 2001 and Hooker 23 sacks amped in	of same and depth and found dumped 4 lup circu a of gel n a 54 sacks	it open sacks o	fee
rectified in the hole. It is a feet for each place of Plugging Contractor.	Checkor Filled cement pump a filled to base	d the W/sar With nd pun to 50 e of c	hole to do to 320 bailer. ped in 2 00'. Pr cellar.	34721 : 2001 and Hooker 23 sacks amped in	of same and depth and found dumped 4 lup circu a of gel n a 54 sacks	it open sacks o	fee
ntroducing it into the hole. It feet for each pl	Checker Filled cement pump a filled to base	d the W/sar With nd pun to 50 e of c	hole to do to 320 bailer. ped in 2 00'. Pr cellar.	34721 : 2001 and Hooker 23 sacks amped in	of same and depth and found dumped 4 lup circu a of gel n a 54 sacks	it open sacks o	fee
ntroducing it into the hole. It feet for each pl	Checkon Filled cement pump a filled to base PLUGGI	d the W/sar With nd pun to 50 e of c	hole to do to 320 bailer. nped in 2 00'. Procellar. PLETED	34721 : 2001 and Hooker 23 sacks amped in	of same and depth and found dumped 4 lup circu of gel n 54 sacks	it open sacks o	fee
ntroducing it into the hole. It feet for each pl	Checker Filled cement pump a filled to base PLUGGI Knight Jhase,	d the W/sar With nd pun to 50 e of c	hole to ad to 320 bailer. aped in 2 00'. Pi cellar. APLETED	3472'; 20' and Hooker 23 sacks amped in	of same and depth and found dumped 4 lup circu of gel n 54 sacks	it open sacks or lating mud, s of ceme	ent.
ntroducing it into the hole. It feet for each plants of Plugging Contractor	Checkon Filled cement pump a filled to base PLUGGI	d the W/Sar With nd pun to 50 e of c Casin Kansa	hole to ad to 320 bailer. pped in 2 00'. Prediction is needer Pulling ENTY OF the cowledge of the	3472 : 300 and Hooker 23 sack; imped in RICE (employee of facts, statem	of same and depth and found dumped b lup circl a of gel n 54 sacks K of this sheet)	it open sacks or lating nud, s of ceme	ent.
ntroducing it into the hole. It feet for each plants of Plugging Contractor	Checkon Filled cement pump a filled to base PLUGGI	d the W/sar With nd pun to 50 e of co	hole to ad to 320 bailer. pped in 2 00'. Prediction is needer Pulling ENTY OF the cowledge of the	3472 : 300 and Hooker 23 sack; imped in RICE (employee of facts, statem help me God Man I facts)	of same and depth and found dumped b up circu of gel n 54 sacks when sand matter contents, and matter contents, and matter contents.	it open sacks of lating mud, sof ceme	ent.
ntroducing it into the hole. If	Checkon Filled cement pump a filled to base PLUGGI	d the W/sar With nd pun to 50 e of co	hole to do to 320 bailer. ped in 2 00'. Pr cellar. PLETED description is needly Pullir sowledge of the do correct. So (Signature)	3472 : 300 and Hooker 23 sack; imped in RICE (employee of facts, statem help me God Man I facts)	of same and depth and found dumped b lup circu cof gel n 54 sacks where or (was cents, and matter hase, Kar	it open sacks of lating mud, sof ceme	ent.
ntroducing it into the hole. It feet for each plants and the second plants are second plants and the second plants are second plants. ATE OF	Checkon Filled cement pump a filled to base PLUGGIN Chase, KANSAS I, Noel ath, says: That I that the same a	d the W/sar With nd pun to 50 e of co	hole to do to 320 bailer. aped in 2 00'. Procellar. APLETED Idescription is needing Pulling assume the process of the process	34721 : 200 and Hooked 23 sack: 1mped in RICE (employee of facts, statem help me God Mand for the Rich facts and facts are the facts and facts are the facts	of same and depth and found dumped b up circu of gel n 54 sacks when sand matter hase Kar	it open sacks of lating mud, sof ceme	ent.
ntroducing it into the hole. It feet for each plants and the second plants are second plants. The second plants are second plants are second plants. ATE OF	Checkon Filled cement pump a filled to base PLUGGIN Chase, KANSAS I, Noel ath, says: That I that the same a	d the W/Sar With nd pun to 50 e of co	hole to do to 320 bailer. ped in 2 00'. Pr cellar. PLETED Idescription is needing Pulling assumed to 12 Inight assumed correct. So (Signature)	34721 : 200 and Hooked 23 sack: 1mped in RICE (employee of facts, statem help me God Mand for the Rich facts and facts are the facts and facts are the facts	of same and depth and found dumped b lup circu cof gel n 54 sacks where or (was cents, and matter hase, Kar	it open sacks of lating mud, sof ceme	ent.

MELL LOG BUREYU KANSAS GEOLOGICAL SOCIETY 4.2 bear National Ph. 1.13g., Wichite, Kansan



Company MAZDA OIL CORP. Farm Henderson

No. 1-G

7. 11 SEC. 27 rl8W NW NW NN

Total Capth. 35261

Comm 2-22-48

Comp. 3-18-48

Shor or freeded. Acidized 250 Gals.


Contractor Earl F. Jakofield

830en 5-8-48

CASINO:

8-5/8" 1248' Comented 5-1/2" 3515! Camented County, Ellis

Stavation.



Production, Deptho. 3732 BO, & no water.

Figures Individe Bottom or Formations

sand, clay & gravel 40 shale blue 104 shale 205 285

lime strks & shale shale w shells 475 shale & red bed 500 red bed sand 535 shala & sand 620 sand & iron P. 685

shale 720 sand 745 sand & shale 088 shala & shalls 980 redbed, shale and

line shells 1145 red bed 1241 anhydrite 1299 shalc 1355 shale & rod bed 1525 shalo & salt 1745 shale 1800lime & shale 2175 lime shale brks 2229 lime & shala 2287 lime & shale brks 2380

lime & shale 2567 lime 2620 lime & shale 2616 lime 2856 lime & shale 2914 lime û shale brks 2972 lina 3010

lime & shale 3054 lime & cherty 3091 lime 3192 lime & shale 3266 lima 3359 lime & cherty lime & shale 3388 3472

conglomerate & chert 3490 conglomerate 3499 Simpson Dolomite 3513 chert & green shale 3515 Arbuckle RTD 3517

Top Topeka

2940

Drilled Deeper: Dolomite

3526

Total Depth

100° oil in hole at 3517 200' oil in hola at 3519 300' oil in hole at 600' oil in hole at 3522 3523 1500'oil in hole at 2520 2500 oil in hole 2 hrs. after drilling to 3526.

Swabbed 11 BO in 1 hr. 2300' off bottom.

Acidized with 250 gallons. Pumped 19 BOPH - 6 hours. Did not lower fluid level. below 2350' off bottom.

I. P. 3732 BO, no wtr Deptho.

Pot. 3000 Bbls. Maximum

Tops; derrick floor level Topeka 2911 Heebner 3170 Dodge 3190 Lansing K. C. 3212 Sft zones 3249-51 sft zones 3292-96 sft zone 3302-06 colicastic sft zone 3374-76 Base Kansas City B.P. Conglomerate 3466 Simpson Dolomite 3497 Simpson Shale 3500 Ero. Arbuckla 3511

3513

Solid Arbuckle

1