

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
212 North Market, Insurance Bldg.

WELL PLUGGING RECORD

212 North Market, Insurance Bidg. Wichita, Kansas					тwp. <u>16</u> S Rg		-19w)
NORTH		E/CNW&SW&"	or footage fro	m lines	SE SE SW		
	Lease Owner_		Herrman	. Farmer,	ine.		1
	Lease Name	370 W			l Kaneae	Well No	
 !!	1	/ell (completed				rv	
	Date well com			Diy Hole).		- J	.19.
	1	plugging filed				12/9	1961
	Application for	plugging appro	ved				_19 <u>61</u> _
	Plugging comm	enced				12/9	19.61
		leted				Dry	_19_ <u>61</u>
<u> </u>	Reason for abai	ndonment of we	ll or producin	g formation			 -
	TEdia			1			
					or its agents be		
Locate well correctly on above Section Plat	menced?		Yes	addir Division		note plugging	was com-
Name of Conservation Agent who sup	pervised plugging of th	is well E	ldon Pet	ty			
Producing formation	I	Depth to top	Botton	n	_ Total Depth o	of Well380	09_Feet
Show depth and thickness of all water	r, oil and gas formation	ns.					
OIL, GAS OR WATER RECOR	.DS					CASING RE	CORD
FORMATION	<u> </u>	FROM	T	6175	AUT 111	1	
PURMATION	CONTENT	FRUM	TO	SIZE	PUT IN	PULLED	QUT
	-		 	 		 	 :
			-	 			
	-	<u> </u>					
	 		ļ	ļ			
S	irst Plug at 4 econd Plug at hird Plug at 3	200' with	20 sacks	cement			
	· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·				
						2	
			·		The COMM	15c10h	
			·- ·- ·- ·- ·- ·- ·- ·- ·- ·- ·- ·- ·- ·		Section 18 Contraction	, 12-14-6	1
			·	٠, ٢	ادر ب)\"	
					0502	"112101"	
					" N		
					 -		
	/TE additions	l description is nece		Catable days	····		
Name of Plugging Contractor	John	O. Farmer,	Inc.	or emis sneet)			
Address	P. O. Box 35	2 <u>, Russell</u>	Kansas				
			· · · · · · · · · · · · · · · · · · ·	· - · <u>- · · · · · · · · · · · · · · · ·</u>			
STATE OF Kansa	ohn O. Farmer	JNTY OF	Russel		, 85.		
well, being first duly swom on oath		omiladas et il	employee of	owner) or (or	wner or operator) of the above	-described
above-described well as filed and th	at the same are true a	nd correct. So	hein me Cod	ents, and mat	ters nerein conta	ined and the	log of the
		(Signature)	XOM	UO. 7	armo	2N	
		/	170		rresident	J	
		/7	J 1	chita, R	(Address)	nsas	
SUBSCRIBED AND SWORN TO be	fore me this 11th	h day of	Decemb	er	, 19.	61	
	18/64	_	I	Orothy R	atts	Notary	Public.
My commission expires				-			

15.165.00282-0000

		ΑĐ	DRESS.	_Р.	.ف	Box 3	2,	Russ	ell,	Ken	3 25	
3.	640 Acres	•		· ·	4	ì						
	- 1 -					SEC						
- 		- <u>- </u>				ATINGIC						
160	- -[- 	160				370 W						
\dashv						ED11/28						
++						PRODUCTION						
11	1					IZ 4 SI	C	4 SW		3 0 _, i	North	of So
160	 	150				, <u> </u>			West Lin			
						e ta sea leve						
Loca	te well con	rectly	CHI	ARACTER	OF '	WELL (Oil, g	28 OF	dryhole)	נזע			
		·		OIL O	R GAS	SANDS OR	ZONE	s	· · · · · · · · · · · · · · · · · · ·			,
	Nom	e		From	To			Name	_		From	To
<u>'</u>				<u> </u>		_ 4						<u> </u>
2				-	 	$-\frac{5}{6}$						-
3	Parla	otion I	ecord if	Am	ļ.			Sh	ot Recerc			<u> </u>
Fon	nation	From		· ,	f Shots		ormati		From	To	Şizə	of She
			-	1						•		
	_				CASI	NG RECORD						
6:		76.4		Amount Set							Packer Record opth Set Mak	
Size	W1.	Thds.	Make	Ft.	+"	1. [1.	In.	3128	Length	Dep	in Ser	Mak
	-			 	+	+	 			1-	 	
									1	<u> </u>		
ner Rec	ord: Amo	ınt.		Ki	nd		To	·		Sottom.		
		·				G AND MUD						
Size -	Ft. In.	-4	nt Gal	Chemical Gal. Mak		Method of Cementing	A	fauor	Mudding Method		Result (See No	
5 6	162	115					+-			"	(388 (1018)	
<u>, 7/</u>		1 4 4 7	'				- 					
ote: W	hat metho	d wait	used to	protect,	sands	if outer stri	ngs w	ere pull	ed?			
OTE: W	ere botton	hole p	ynds mee	4?	ı	f so, state ki	nd, de	oth set	and resul	ts obt	ained	
						OLS USED						
otary To	ols were u	sed fro	m <u>O</u>	_ feet to	3	309cable to	ols w	ere used	from	(feet to	·
	feet, a	nd from		fee	t to	fe	et, an	d from _		_ feat	to	
		<u> </u>	14.			Ro	car	<i>y</i>	<u>.</u>		_	
nge Rig							****		· · · · · · · · · · · · · · · · · · ·			
/pe Rig	•			INII	IAL P	RODUCTION	1501				٠.	
ype Rig escribe		. wheth	erby Pro			place or conju		by pump	in g	·	٠.	
		: wheth	erbyf16			٠, ٠		by pump	ing	· · ·	·.	
escribe	initial test	· · · ·	<u> </u>	w throu	gh tul	٠, ٠	g or I			test		Wo

Formation	Тор	Bottom	Formation , 4	Тор	Seltem
Burface	0	162		T.,	
Shale	162	525	TOPS: Log	ا ا	
Shale & Sand	535	675	Weebner	3382	(-1298)
Band.	675	880	Toronto	3402	(-1318)
Shale, Redbed,			Lansing/KC	3428	(-1344)
Shells	880	1050	Marmathon Chert	3733	(-1649)
Shale & Shells	1050	1263	Reagan (Shaley)	3776	(-1692)
Anhydrite	1263	1308	Reagan	3788	(-1704)
Shale & Shells	1308	1690	T. D.	3809	(-1725)
Shale & Salt	1690	1990			
Shale & Lime	1990	2190			.
Lime & Shale	2190	2530			
Shale & Lime	2530	3175	•		
Lime & Shale	3175	3669			-
Line	3669	3715	-		
Lime & Shale	3715	3809			
r. D.	3809				
			•		
	ļ				
			1/2		
• .			ALCHING WILLIAM SOM		
,					, ,
			Office Contraction		
4			11/3 7 5		
•			13 0		· .
	į		WE TO		
-			136	4	
			118		
			di		
•			F	-	
			1	. '	
			• • •	4	
•			•		
			;		
	}	ļ j			ļ

I, the undersigned, being first duly sworn upon act, staticomplete according to the records of this office and to the best

he and title of representative of company

My Commission expires 5/18/64

Notary Public.