KCC OIL/GAS REGULATORY OFFICE		15.171.20467.0	XXXX
TE 10/11/94	•	[] New Situ	ation
PERATOR Slawson Exploration Co. Inc. # 3988	<u>.</u>	[_X] Response [] Follow-u	
AME 621 N. Robinson, #490	LOCATION SW	,SEC <u>16</u> ,T <u>18</u>	_S,R31W
DDRESS Oklahoma City, OK 73102	LEASE Reifschnei	ider 0 Well #1	
HONE NO. PER. OTHER	COUNTY Scott	-171-20,467	·
EASON FOR INVESTIGATION: Alternate II cemer	nting	· ·	<u>8</u>
			INSPECT ION
			INSE
ROBLEM: Top of cement at 985'			EASE
PERSON(S) CONTACTED: Steve Slawson			
INDINGS: Halliburton set a CIBP at 120	00'.		
Perforated casing at 900°. Allied pumped in	n 175 sx 60/40 Pozmi:	x 6% gel and 50 s	k common
cement. Circulated cement to pit.		<u> </u>	WHE AINT
Started job at 1 p.m. and completed it at 2	p.m.		E CO
·		•	
		photos taken	:
ACTION/RECOMMENDATIONS: _Need to see bond 1	og that shows cement	to 985' before A	lternate ED GEORI
II cementing is complete.			9
	en ane (MATORITION	FIE
	•	OCT 10 ID	8/
Retain 1 copy Joint District Office	0	mustall Steve Mi	
	KV	DECAG III	ddleton