

State of Kansas



# State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian  
WICHITA, KANSAS 67217

VERBAL PERMIT FORM  
(To Be Filed By Plugging Agent)

RECEIVED  
STATE CORPORATION COMMISSION

MAY 27 1975

CONSERVATION DIVISION  
Wichita, Kansas

J. Lewis Brock  
Administrator  
500 Insurance Building  
Wichita, Kansas 67202

Dear Sir:

Mr. Jackson of Kaiser-Francis has this

date requested permission to plug the following described well:

Mr. Jackson guarantees payment of the plugging fee.

Operator's full Name: Kaiser-Francis

Complete Address: 4120 E. 51st. St., Tulsa, Okla.

Lease Name: Petersilie "A" Well No. 1

Location: C S/2 SW SE Sec. 1 Twp. 20 Rge. (E)(W) 24

County: Ness Total Depth 4467' Oil Well

Gas Well  Input Well  SWD Well  D & A XX TA (3-15-75)  
~~Lost Hole~~

Mr. Jackson was instructed to plug the well as follows:

Mix & pump down 8 5/8 csg with 10 sk gel & water W 200 lbs hulls -

release plug & 80 sk 50-50 poz 6% -displace with 8 sk gel & water &

cap 8 5/8 with 20 sk 50-50 poz 6% by Sun Cementing Co. ~~XXXXXXXXXX~~

Very truly yours,

*Leo Moray*

15-135-21015-0000

State of Kansas



# State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water)

P.O. Box 17027 3830 S. Meridian  
WICHITA, KANSAS 67217

VERBAL PERMIT FORM  
(To Be Filed By Plugging Agent)

RECEIVED  
STATE CORPORATION COMMISSION

MAR 18 1975

CONSERVATION DIVISION  
Wichita, Kansas

J. Lewis Brock  
Administrator  
500 Insurance Building  
Wichita, Kansas 67202

Dear Sir:

Mr. Pruner of Kaiser-Francis has this

date requested permission to plug the following described well:

Mr. Pruner guarantees payment of the plugging fee.

Operator's full Name: Kaiser-Francis

Complete Address: 4120 E. 51st St. Tulsa, Okla.

Lease Name: Petersilie  
~~XXXXXXXXXX~~ "A" Well No. 1

Location: C S/2 SW SE Sec. 1 Twp. 20 Rge. (E)(W) 24

County: Ness Total Depth 4467' Oil Well

Gas Well  Input Well  SWD Well  D & A TA Lost Hole

Mr. Pruner was instructed to plug the well as follows:

Gun pits, fill hole with heavy mud & cap 8 5/8 csg with steel plate  
until ready to complete as "SWD".

Very truly yours,

Geo. H. Murrell  
Conservation Division Agent