MA. NO.

CONSERVATI	ORATION COMMISSION ON DIVISION - PLUGGING SECTION	NW SW SE, SEC.	<u> </u>	17 S, R 16
200 COLORA	DO DERBY BUILDING			rom S section
WICHITA, KANSAS 67202				om E section
	S PLUGGING REPORT			
	icense / 5131	-		Well #1
A1 •	Thunderbird Drilling, Inc.		· ·	117.91
	P. O. Box 18407	_ Well Total D	epth36	628
	Wichita, KS 67218	Conductor PI	pe: Slze	feet
		_ Surface Cast	ng: SIze <u>8</u>	5/8 feet 346
Abandoned	Oli WeilGas Well			
	as hereinafter indicated			
	Contractor Thunderbird Drilling		License	Number 5131
Address	P. O. Box 18407, Wichita, KS (0/218		
Company to	plug at: Hour: 11:00 am Day:	3 Month:	April	Year:19 <u>85</u>
Binaalaa (proposal received from	Ed Cook		
riugging i				
(company r	name) Thunderbird	 	(phone) <u>316-685-</u> 1
	fill hole with heavy mud and s			
were: to	fill hole with heavy mud and sp	pot cement through		
were: to	fill hole with heavy mud and spat 1140 with 50 sx cement	pot cement through		
were: to	fill hole with heavy mud and sp	pot cement through		
lst plug a 2nd plug a 3rd plug a	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement	pot cement through	drill pipe	
lst plug a 2nd plug a 3rd plug a	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge	pot cement through	drill pipe	
lst plug a 2nd plug a 3rd plug a 4th plug b	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to	pot cement through	drill pipe	
lst plug a 2nd plug a 3rd plug a 4th plug b	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge	pot cement through	drill pipe sx cement Steve Du	
lst plug a 2nd plug a 3rd plug a 4th plug b 6th plug t	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 sx	o surface with 10 k cement oposal Received by	sx cement Steve Du	rrant TECHNICIAN)
lst plug a 2nd plug a 3rd plug a 4th plug b 6th plug t	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 ss Plugging Pr	o surface with 10 k cement oposal Received by	sx cement Steve Du	rrant TECHNICIAN)
lst plug a 2nd plug a 3rd plug a 4th plug b 6th plug t	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 sx	o surface with 10 k cement oposal Received by	sx cement Steve Du	rrant TECHNICIAN)
lst plug a 2nd plug a 3rd plug a 4th plug b 6th plug t Plugging a Operation	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 ss Plugging Pr	o surface with 10 coment oposal Received by All Pa	sx cement Steve Du (rt	rrant TECHNICIAN) None X Year:19 <u>85</u>
lst plug a 2nd plug a 3rd plug a 4th plug b 6th plug b Plugging a Operation ACTUAL PL	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 spans propertions attended by Agent?: s Completed: Hour: 12:30 pm Day	surface with 10 cement oposal Received by All Pa : Month	sx cement Steve Du (rt : April t. 2nd plug	rrant TECHNICIAN) None X Year:19 85
lst plug a 2nd plug a 3rd plug a 4th plug b 6th plug b Plugging a Operation ACTUAL PL sx cement,	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 ss Plugging Pr Operations attended by Agent?: s Completed: Hour: 12:30 pmDay	o surface with 10 k cement oposal Received by All Pa : 3 Month with 50 sx cementement, 4th & 5th p	sx cement Steve Du (rt : April t. 2nd plug lugs - soli	rrant TECHNICIAN) None X Year:19 85 at 750' with d
lst plug a 2nd plug a 3rd plug a 3rd plug a 4th plug b 6th plug b 6th plug t Plugging Operation ACTUAL PL sx cement, plug at 40	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 sx Plugging Pr Operations attended by Agent?: s Completed: Hour: 12:30 pmDay UGGING REPORT 1st plug at 1140 , 3rd plug at 360' with 40 sx ce O' cement to surface with 10	o surface with 10 k cement oposal Received by All Pa : 3 Month with 50 sx cementement, 4th & 5th p	sx cement Steve Du (rt : April t. 2nd plug lugs - soli	rrant TECHNICIAN) None X Year:19 85 at 750' with 5 d bridge - hull late rat hole
lst plug a 2nd plug a 3rd plug a 4th plug b 6th plug b Plugging a Operation ACTUAL PL sx cement,	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 sx Plugging Pr Operations attended by Agent?: s Completed: Hour: 12:30 pmDay UGGING REPORT 1st plug at 1140 , 3rd plug at 360' with 40 sx ce O' cement to surface with 10	o surface with 10 k cement oposal Received by All Pa : 3 Month with 50 sx cementement, 4th & 5th p	sx cement Steve Du (rt : April t. 2nd plug lugs - soli	rrant TECHNICIAN) None X Year:19 85 at 750' with d
lst plug a 2nd plug a 3rd plug a 3rd plug a 4th plug b 6th plug b 6th plug t Plugging Operation ACTUAL PL sx cement, plug at 40	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 sx Plugging Pr Operations attended by Agent?: s Completed: Hour: 12:30 pmDay UGGING REPORT 1st plug at 1140 , 3rd plug at 360' with 40 sx ce O' cement to surface with 10	o surface with 10 k cement oposal Received by All Pa : 3 Month with 50 sx cementement, 4th & 5th p	sx cement Steve Du (rt : April t. 2nd plug lugs - solic ug to circu	rrant TECHNICIAN) None X Year:19 85 at 750' with 5 d bridge - hull late rat hole APR 1 2 1005
lst plug a 2nd plug a 3rd plug a 3rd plug a 4th plug b 6th plug b 6th plug t Plugging Operation ACTUAL PL sx cement, plug at 40	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 sx Plugging Pr Operations attended by Agent?: s Completed: Hour: 12:30 pmDay UGGING REPORT 1st plug at 1140 , 3rd plug at 360' with 40 sx ce O' cement to surface with 10	o surface with 10 k cement oposal Received by All Pa : 3 Month with 50 sx cementement, 4th & 5th p	sx cement Steve Du (rt :April t2nd plug lugs - solicu ug to circu	rrant TECHNICIAN) None X Year:19 85 at 750' with 5 d bridge - hull late rat hole ICO ((',')) CORPORATION CONTESS APR 1 2 1985
lst plug a 2nd plug a 3rd plug a 3rd plug a 4th plug b 6th plug b 7th plug b 6th plug t 8th plug b 9th plug b 9th plug b 1th plug b	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 sx Plugging Pr Operations attended by Agent?: s Completed: Hour: 12:30 pm Day uGGING REPORT 1st plug at 1140 g 3rd plug at 360' with 40 sx co of cement to surface with 10 sx cement.	Surface with 10 coment oposal Received by AllPa :_3Month with 50 sx cement ement, 4th & 5th p sx cement, 6th p1	sx cement Steve Du (rt :_April t. 2nd plug lugs - solid ug to circu STATE (rrant TECHNICIAN) None X Year:19_85 at 750' with 5 d bridge - hull late rat hole APR 1 2 1985 - 85 SERVATION COMMISSION VICTORIAN
lst plug a 2nd plug a 3rd plug a 3rd plug a 4th plug b 6th plug b 7th plug b 6th plug t 8th plug b 9th plug b 9th plug b 1th plug b	fill hole with heavy mud and spat 1140' with 50 sx cement at 750' with 50 sx cement at 360' with 40 sx cement solid bridge mulls - plug at 40' cement to co circulate rat hole with 10 sx Plugging Pr Operations attended by Agent?: s Completed: Hour: 12:30 pm Day uGGING REPORT 1st plug at 1140 g 3rd plug at 360' with 40 sx co other cement to surface with 10 sx cement.	Surface with 10 coment oposal Received by AllPa :_3Month with 50 sx cement ement, 4th & 5th p sx cement, 6th p1	sx cement Steve Du (rt :_April t. 2nd plug lugs - solid ug to circu STATE (rrant TECHNICIAN) None X Year:19_85 at 750' with 5 d bridge - hull late rat hole APR 1 2 1985 - 85 SERVATION COMMISSION VICTORIAN

FORM CP-2/3 Rev.01-84