Form CP-3 Rev. 6-26-62

KANSAS KANDAD STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT STATE CORPORATION CONMISSION APR 19 1985 4-19.65 CONSCHUATION DIVISION Wichia, Kanses

J. P. Roberts Assitant Director 500 Insurance Building 212 North Market Wichita 2, Kansas

mnlata Addressi	James T. Armer 424 N Chautauqua Vichita, Kens
Omprese waaress.	Hays Well No. 1
ease Name	OSW SW Sec. 7 Twp. 18 Rge. (E) (W) 2
ocation	Ness Total Depth 4600
bandoned Oil Well	Cas Well Input Well SWD Well D & A x
ther well as hereafter	indicated:
Disease Contractors	Terrel Drg Co
lddracat	Russell, Kans License No.
Operation Completed: The Above well was plug	Hour 11PM Day 12 Month 4 Year 65
8 5/8" 200' circu	alated with cement.
8 5/8" 200' circu Circulated hole w	with heavy mud, set plug at 700 displaced 20 sex
8 5/8" 200' circu Circulated hole w	vith heavy mud, set plug at 700! displaced 20 sex
8 5/8" 200' circu Circulated hole w cement through dr cement displaced	vith heavy mud, set plug at 700! displaced 20 sex cill pipe, heavy mud to 200!, set plug and 20 sex throughdrill pipe, heavy mud to 55!, set plug, hulls
8 5/8" 200' circu Circulated hole w cement through dr cement displaced	vith heavy mud, set plug at 700! displaced 20 sex
8 5/8" 200' circu Circulated hole w cement through dr	vith heavy mud, set plug at 700! displaced 20 sex cill pipe, heavy mud to 200!, set plug and 20 sex throughdrill pipe, heavy mud to 55!, set plug, hulls
8 5/8" 200' circu Circulated hole w cement through dr	vith heavy mud, set plug at 700! displaced 20 sex cill pipe, heavy mud to 200!, set plug and 20 sex throughdrill pipe, heavy mud to 55!, set plug, hulls
8 5/8" 200' circu Circulated hole w cement through dr	vith heavy mud, set plug at 700! displaced 20 sex cill pipe, heavy mud to 200!, set plug and 20 sex throughdrill pipe, heavy mud to 55!, set plug, hulls
8 5/8 200 circulated hole we cement through dreament displaced filled to bottom	with heavy mud, set plug at 700' displaced 20 sax cill pipe, heavy mud to 200', set plug and 20 sax throughdrill pipe, heavy mud to 5h', set plug, hulls cellaf with cement.
8 5/8 200 circulated hole we cement through dreament displaced filled to bottom	vith heavy mud, set plug at 700! displaced 20 sex cill pipe, heavy mud to 200!, set plug and 20 sex throughdrill pipe, heavy mud to 55!, set plug, hulls