Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: VAL ENERGY, INC	License Number: 5822
Operator Address: 200 W DOUGLAS SUITE 520 WICHITA, KS 6	57202
Contact Person: K. TODD ALLAM	Phone Number: (316) 263 - 6688
Permit Number (API No. if applicable): 15-15-007-23435	Lease Name & Well No.: DIEL & CO 5-21
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW _SW _NW _SE
Settling Pit Drilling Pit	Sec. 21
Workover Pit ✓ Haul-Off Pit	1723 Feet from North / South Line of Section
	2607 Feet from ✓ East / West Line of Section
	BARBER County
f no, how were the sides and bottom sealed to prevent downward migration o	of the pit contents?
Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration o CLAY BOTTOM	
f no, how were the sides and bottom sealed to prevent downward migration o	of the pit contents? RECEIVED KANSAS CORPORATION COMMISSION
f no, how were the sides and bottom sealed to prevent downward migration o	RECEIVED
If no, how were the sides and bottom sealed to prevent downward migration o	RECEIVED KANSAS CORPORATION COMMISSION MAY 1 1 2010
If no, how were the sides and bottom sealed to prevent downward migration of CLAY BOTTOM Abandonment procedure of pit: REMOVE FLUIDS, LET DRY & COVER	RECEIVED KANSAS CORPORATION COMMISSION MAY 1 1 2010 CONSETERATION AND AND AND AND AND AND AND AND AND AN
Abandonment procedure of pit: REMOVE FLUIDS, LET DRY & COVER	RECEIVED KANSAS CORPORATION COMMISSION MAY 1 2010 CONSETERATE AND ACCOUNTY WICHT For
The undersigned hereby certifies that he / she is Abandonward hereby certifies that he / she is Abandonward hereby certifies that he / she is Abandonward migration of CLAY BOTTOM	RECEIVED KANSAS CORPORATION COMMISSION MAY 1 1 2010 CONSETTABLE AND
Abandonment procedure of pit: REMOVE FLUIDS, LET DRY & COVER	MAY 1 1 2010 CONSERVATION COMMISSION CONSERVATION COMMISSION WICHT For
Abandonment procedure of pit: REMOVE FLUIDS, LET DRY & COVER The undersigned hereby certifies that he / she is Abandonment is true and correct to a duly authorized agent, that all information shown hereon is true and correct to	MAY 1 1 2010 CONSERVATION COMMISSION WICHT ForVAL ENERGY, INC(Co.), to the best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: REMOVE FLUIDS, LET DRY & COVER The undersigned hereby certifies that he / she is	MAY 1 1 2010 CONSERVATION COMMISSION WICHT ForVAL ENERGY, INC(Co.), to the best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: REMOVE FLUIDS, LET DRY & COVER The undersigned hereby certifies that he / she is	ANSAS CORPORATION COMMISSION MAY 1 1 2010 CONSERVAL: WICH TO
to no, how were the sides and bottom sealed to prevent downward migration of CLAY BOTTOM CLAY B	MAY 1 1 2010 CONSERVATION COMMISSION WIGHT Tor VAL ENERGY, INC (Co.), to the best of his /her knowledge and belief. Signature of Applicant or Agent