

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner National Cooperative Refinery Association Address Third Floor, Rule Building
(Applicant) Wichita, Kansas
Lease (Farm Name) Giinther Well No. 2
Well Location SW SW NE Sec. 16 Twp. 11 Rge. 19 (~~17~~)-(W)
County Ellis Field Name (if any) Giinther
Total Depth 3571' Oil X Gas Dry Hole
Was well log filed with application? Yes/Attached. If not, explain:

Date and hour plugging is desired to begin At Once.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.

(Use an additional sheet if necessary) No exceptions desired

Name of the person on the lease in charge of well for owner C. E. Heilman
Address Box 6, Great Bend, Kansas

Name of Plugging Contractor West Supply Company
Address Chase, Kansas

Invoice covering assessment for plugging this well should be sent to N.C.R.A.
Address Third Floor, Rule Building, Wichita, Kansas
and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION
JAN 4 1954
01-04-54
CONSERVATION DIVISION
Wichita, Kansas

C. R. Sears
Applicant or Acting Agent
Date December 31, 1953.

PLUGGING
FILE SEC 16 T 11 R 19
BOOK PAGE 5 LINE 18



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

January 4, 1954

Well No. 2
Lease Glinther 17
Description SW SW NE 26-11-19W
County Ellis
File No. 5-18

N. C. R. A.
Third Floor
Rule Bldg.
Wichita, Kans.

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Hays, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: J. P. Roberts
J. P. ROBERTS

cc: District Plugging Supervisor