## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Southern Star Central Gas Pipeline	License Number: 33097
Operator Address: 3800 Frederica Street Owensboro, Kentuck	ky 42301
Contact Person: D. Mark Rouse	Phone Number: ( 270 ) 852 - 4490
Permit Number (API No. if applicable): 15-125-01034-00-01	Lease Name & Well No.: Elk City # 54
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW_NE_SE
Settling Pit Drilling Pit	Sec. 26 Twp. 31 R. 13
✓ Workover Pit  Haul-Off Pit	2076' Feet from North / South Line of Section
	952' Feet from 🗸 East / West Line of Section
	Montgomery County
Was an artificial liner used?	pit contents?
Natural clay.	RECEIVED KANSAS CORPORATION COMMISSION
Natural clay.	·
	KANSAS CORPORATION COMMISSION
Natural clay.  Abandonment procedure of pit:	CONSERVATION DIVISION  CONSERVATION DIVISION
Abandonment procedure of pit: Air dried pit, backfilled, and reclaim area.  The undersigned hereby certifies that he / she is Staff Geologist	OCT 15 2007  CONSERVATION DIVISION WICHITA, KS  for Southern Star Central Gas Pipeline (Co.),
Abandonment procedure of pit: Air dried pit, backfilled, and reclaim area.	OCT 15 2007  CONSERVATION DIVISION WICHITA, KS  for Southern Star Central Gas Pipeline (Co.),
Abandonment procedure of pit: Air dried pit, backfilled, and reclaim area.  The undersigned hereby certifies that he / she is Staff Geologist	CONSERVATION DIVISION  OCT 15 2007  CONSERVATION DIVISION WICHITA, KS  for Southern Star Central Gas Pipeline (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit: Air dried pit, backfilled, and reclaim area.  The undersigned hereby certifies that he / she is Staff Geologist	CONSERVATION DIVISION  OCT 1 5 2007  CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Air dried pit, backfilled, and reclaim area.  The undersigned hereby certifies that he / she is Staff Geologist	CONSERVATION DIVISION  OCT 15 2007  CONSERVATION DIVISION WICHITA, KS  for Southern Star Central Gas Pipeline (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit:  Air dried pit, backfilled, and reclaim area.  The undersigned hereby certifles that he / she is Staff Geologist a duly authorized agent, that all information shown hereon is true and correct to the \textstyle{\textstyle	CONSERVATION DIVISION WICHITA, KS  for Southern Star Central Gas Pipeline (Co.), best of his /her knowledge and belief.  Signature of Applicant or Agent