Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

		2001
must	be	Typed

Operator Name: Rosewood Resources, Inc.	License Number: 33019		
Operator Address: RR 1, Box 206, St. Francis, KS 67756-9789			
Contact Person: Tom W. Roelfs	Phone Number: (970) 324 - 1686		
Permit Number (API No. if applicable): 15-023-20793-01	Lease Name & Well No.: Zweygardt 34-19H		
Type of Pit:	Pit Location (QQQQ):		
Emergency Pit Burn Pit	SE NW SW SE		
Settling Pit ✓ Drilling Pit	Sec. 19 Twp. 3S R. 40 ☐ East ✓ West		
Workover Pit Haul-Off Pit	827 Feet from North / ✓ South Line of Section		
	2141 Feet from Fast / West Line of Section		
	Cheyenne County		
Date of closure: 10/1/2007			
Was an artificial liner used? Yes V No			
if no, how were the sides and bottom sealed to prevent downward migration of the pit contents?			
Clay/Bentonite barrier from drilling fluids.			
Clay/Bentonite barrier from drilling fluids.			
Clay/Bentonite barrier from drilling fluids.			
	RECEIVED KANSAS CORPORATION COMMISSION		
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION		
	NOV 0 2 2007		
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION		
Abandonment procedure of pit:	NOV 0 2 2007 CONSERVATION DIVISION		
Abandonment procedure of pit:	NOV 0 2 2007 CONSERVATION DIVISION WICHITA KS		
Abandonment procedure of pit: Pit was allowed to air dry, then backfilled. Production Forema	NOV 0 2 2007 CONSERVATION DIVISION WICHITA KS Rosewood Resources, Inc. (Co.),		
Abandonment procedure of pit: Pit was allowed to air dry, then backfilled. The undersigned hereby certifies that he / she is Production Forema	NOV 0 2 2007 CONSERVATION DIVISION WICHITA KS In for Rosewood Resources, Inc (Co.), the best of his /her knowledge and belief.		
Abandonment procedure of pit: Pit was allowed to air dry, then backfilled. The undersigned hereby certifies that he / she is Production Forema	NOV 0 2 2007 CONSERVATION DIVISION WICHITA KS Rosewood Resources, Inc. (Co.),		
Abandonment procedure of pit: Pit was allowed to air dry, then backfilled. The undersigned hereby certifies that he / she is Production Forema a duly authorized agent, that all information shown hereon is true and correct to the	NOV 0 2 2007 CONSERVATION DIVISION WICHITA KS In for Rosewood Resources, Inc (Co.), e best of his /her knowledge and ballef. Signature of Applicant or Agent		
Abandonment procedure of pit: Pit was allowed to air dry, then backfilled. The undersigned hereby certifies that he / she is	NOV 0 2 2007 CONSERVATION DIVISION WICHITA KS In for Rosewood Resources, Inc (Co.), e best of his /her knowledge and ballef. Signature of Applicant or Agent		
Abandonment procedure of pit: Pit was allowed to air dry, then backfilled. The undersigned hereby certifies that he / she is	NOV 0 2 2007 CONSERVATION DIVISION WICHITA KS In for Rosewood Resources, Inc (Co.), e best of his /her knowledge and ballef. Signature of Applicant or Agent		
Abandonment procedure of pit: Pit was allowed to air dry, then backfilled. The undersigned hereby certifies that he / she is	NOV 0 2 2007 CONSERVATION DIVISION WICHITA KS In for Rosewood Resources, Inc (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent		