## KCC OIL/GAS REGULATORY OFFICES

Date: 10/08/12	District: 1 Case #:
	New Situation Lease Inspection
	Response to Request Complaint
	Follow-Up Field Report
Operator License No: 3842	API Well Number: <u>15-101-22400-00-00</u>
Op Name: Larson Engineering, Inc. dba Larson Operating Company	Spot: NW-NW-SW-NW Sec 11 Twp 19 S Rng 29 E / W
Address 1: 562 W. State Rd. 4	1360 Feet from N/ S Line of Section
Address 2:	Feet from E/W Line of Section
City: Olmitz	GPS: Lat: 38.42007 Long: 100.50216 Date: 10/8/12
State: KS Zip Code: 67564 -8561	Lease Name: Riemann-Suppes Well #: 1-11
Operator Phone #: (620) 653-7368	County: Lane
Reason for Investigation:	
Company requested a state witness to the alt	ernate II cementing job
Company requested a state witness to the air	emate in cementing job.
Problem:	
Alternate II cementing requirements have not	heen met
Automate in combining requirements have not	
Persons Contacted:	
None.	
Findings:	
8 5/8" was set @ 260' with 175 sx cement. 5	1/2" was set @ 4657' with 125 sx cement on the primary
cementing job Company opened the port collar @ 2129'. Swift Services, Inc. pumped 195 sx SMD	
cement, circulating 15 sx to the pit. Closed th	e port collar.
Action/Recommendations: Follow	Up Required Yes No Date:
None. Alternate II cementing requirments ha	ve been met.
SMD cement with 1/4# floseal by Swift Service	
GPS converted footages are 1348' FNL & 151' FWL.	
	į
Verification Sources:	Photos Taken: 0
RBDMS KGS T	A Program
	A Program ourthouse By: En Ma
✓ Other: On-site witness-CFIVED	Eric MacLaren
	RECEIVED
Send I Copy to Conservation Division T 1 0 2012	OCT 1 8 2012 Form:
	OCT 1.9 ZOJS

KCC DODGE CITY \ KCC WICHITA

MA