0;		
ONSERVAT	PORATION COMMISSION ION DIVISION - PLUGGING SECTION	C SE NE , SEC. 13 . 7 27 S. R 19
00 COLOR	ADO DERBY BUILDING	N SE Corner of 3300 feet from \{\foats\} section 1
	KANSAS 67202	660 W SE Corner of
	N'S PLUGGING REPORT	***************************************
perator	License # 5118	
perator:	TGT Petroleum Corp.	County Kiowa
lameå Addrass	209 East William	Well Total Depth 4940 160.55
	Wichita, KS 67202	Conductor Pipe: Sizefeet
		Surface Casing: Size 5/8 feet 477
	Con Woll	Input Well SWD Well D&A X
		5/00
lugging	Contractor Abercrombie Drilli	ing, Inc. License Number 5422
ddress	801 Union Center, Wichita,	KS 67202
		: 3 Month: October Year: 19 84
	o prog cir.	
		II Manage
		Harvey Moore
company	name) Abercrombie	(phone) 316-262-18
company	name) Abercrombie to fill hole with heavy mud a	
company vere:	to fill hole with heavy mud a at 1260° with 50 sx cement	(phone) 316-262-18
company vere: lst plug	Abercrombie to fill hole with heavy mud a at 1260 with 50 sx cement at 600 with 50 sx cement	(phone) 316-262-18
company vere: lst plug	to fill hole with heavy mud a at 1260° with 50 sx cement	(phone) 316-262-18
company vere: lst plug 2nd plug 3rd plug 5th plug	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulls - plug at 40' cement to circulate rat hole with 10	(phone) 316-262-18 and spot cement through drill pipe to surface with 10 sx cement sx cement
company vere: lst plug 2nd plug 3rd plug 5th plug	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulls - plug at 40' cement to circulate rat hole with 10	(phone) 316-262-18 and spot cement through drill pipe to surface with 10 sx cement sx cement
company vere: lst plug 2nd plug 3rd plug 5th plug	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulis - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with ser well with 5 sx Plugging P	(phone) 316-262-18 and spot cement through drill pipe to surface with 10 sx cement sx cement
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme	to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulfs - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with er well with 5 sx Plugging Pont	to surface with 10 sx cement sx cement To sx cement To sx cement Troposal Received by Malway M. Jacay (TECHNICIAN)
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulis - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with er well with 5 sx Plugging P nt Operations attended by Agent?:	to surface with 10 sx cement sx cement roposal Received by Mulway M. Jacay (TECHNICIAN) Part None X
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulis - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with 10 er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da	to surface with 10 sx cement sx cement 10 sx cement Proposal Received by Relay W. Jacey (TECHNICIAN) All Part None X sy:3 Month:October Year:1984
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulis - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with 10 er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da	to surface with 10 sx cement sx cement roposal Received by Mulway M. Jacay (TECHNICIAN) Part None X
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulis - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da	to surface with 10 sx cement sx cement Troposal Received by Malway M. Jacay (TECHNICIAN) All Part None X ay: 3 Month: October Year:1984 60' with 50 sx cement, 2nd plug at 600' with 50
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio ACTUAL P	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulfs - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with 10 er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am 0a LUGGING REPORT 1st plug at 120 t. 3rd & 4th plugs - solid brid	to surface with 10 sx cement sx cement roposal Received by Malway W. Jacay (TECHNICIAN) All Part None X All Part None X 60' with 50 sx cement, 2nd plug at 600' with 50 dge - hulls - plug at 40' cement to surface
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio ACTUAL P sx cemen with 10	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulls - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da lugging REPORT 1st plug at 120 t. 3rd & 4th plugs - solid brid sx cement, 5th plug to circular	to surface with 10 sx cement sx cement Troposal Received by Relating W. Jacky (TECHNICIAN) All Part None X All October Year: 1984 60' with 50 sx cement, 2nd plug at 600' with 50 dge - hulls - plug at 40' cement to surface te rat hole with 10 sx cement, 6th plug to
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio ACTUAL P sx cemen with 10	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulls - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da lugging REPORT 1st plug at 120 t. 3rd & 4th plugs - solid brid sx cement, 5th plug to circular	to surface with 10 sx cement sx cement To sx cement roposal Received by Malard W. Jacay (TECHNICIAN) AllPartNoneX ay:3Month:OctoberYear:1984 60' with 50 sx cement, 2nd plug at 600' with 50 dge - hulls - plug at 40' cement to surface te rat hole with 10 sx cement, 6th plug to and plugged water well with 5 sx cement. RECEIVED
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio ACTUAL P sx cemen with 10	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulls - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da lugging REPORT 1st plug at 120 t. 3rd & 4th plugs - solid brid sx cement, 5th plug to circular	to surface with 10 sx cement sx cement To sx cement roposal Received by Malard W. Jacay (TECHNICIAN) AllPartNoneX ay:3Month:OctoberYear:1984 60' with 50 sx cement, 2nd plug at 600' with 50 dge - hulls - plug at 40' cement to surface te rat hole with 10 sx cement, 6th plug to and plugged water well with 5 sx cement.
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio ACTUAL P sx cemen with 10	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulls - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da lugging REPORT 1st plug at 120 t. 3rd & 4th plugs - solid brid sx cement, 5th plug to circular	to surface with 10 sx cement sx cement To sx cement roposal Received by Malard W. Jacay (TECHNICIAN) AllPartNoneX ay:3Month:OctoberYear:1984 60' with 50 sx cement, 2nd plug at 600' with 50 dge - hulls - plug at 40' cement to surface te rat hole with 10 sx cement, 6th plug to and plugged water well with 5 sx cement. RECEIVED
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio ACTUAL P sx cemen with 10 circulat	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulls - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with 10 er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da tugging REPORT 1st plug at 120 t. 3rd & 4th plugs - solid brid sx cement, 5th plug to circular e mouse hole with 10 sx cement	to surface with 10 sx cement sx cement roposal Received by Relaxa W. Jacky (TECHNICIAN) All Part None X ay: 3 Month: October Year: 1984 60' with 50 sx cement, 2nd plug at 600' with 50 dge - hulls - plug at 40' cement to surface te rat hole with 10 sx cement, 6th plug to and plugged water well with 5 sx cement. RECEIVED STATE CORPORATION COMMISSION
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio ACTUAL P sx cemen with 10 circulat	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulls - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with 10 er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da tugging REPORT 1st plug at 120 t. 3rd & 4th plugs - solid brid sx cement, 5th plug to circular e mouse hole with 10 sx cement Used 60/40 Pozmix 2% gel 3% c	to surface with 10 sx cement sx cement 10 sx cement roposal Received by Malay M. Jacay (TECHNICIAN) AllPartNoneX ay: 3
lst plug 2nd plug 3rd plug 5th plug 6th plug Plug wat ceme Plugging Operatio ACTUAL P sx cemen with 10 circulat	Abercrombie to fill hole with heavy mud a at 1260' with 50 sx cement at 600' with 50 sx cement solid bridge hulls - plug at 40' cement to circulate rat hole with 10 to circulate mouse hole with 10 er well with 5 sx Plugging P nt Operations attended by Agent?: ns Completed: Hour: 8:00 am Da tugging REPORT 1st plug at 120 t. 3rd & 4th plugs - solid brid sx cement, 5th plug to circular e mouse hole with 10 sx cement Used 60/40 Pozmix 2% gel 3% c	to surface with 10 sx cement sx cement 10 sx cement roposal Received by Release (TECHNICIAN) All Part None X ay: 3 Month: October Year:1984 60' with 50 sx cement, 2nd plug at 600' with 50 dge - hulls - plug at 40' cement to surface te rat hole with 10 sx cement, 6th plug to and plugged water well with 5 sx cement. RECEIVED STATE CORPORATION COMMISSION C by Halliburton Is necessary, use BACK of HINSPAPEN VIVISION Wichita, Kansas

NOV 1 3 1984

FORM CP-2/3 Rev.01-84