| ` | 1031319 4-3 | 4-3 API NUMBER 15-101-21,697-6000 | | | |
|--|--|---|---|--|--|
| STATE CORPOR Conservation 200 Colorado | ATION COMMISSION DIVISION - PLUGGING SECTION DERBY BUILDING | NW NW SE , SEC. | 33 , T_ 1 | 16 S, R 27 W/XE | |
| WICHITA, KAN | ISAS 67202 | | | m S section line | |
| TECHNICIAN'S | PLUGGING REPORT | 2310 | feet from | m E section line | |
| Operator Lic | 31283 | Lease Name Ande | rson Trust | Helf # | |
| | Rheem Resources, Inc. | County Lane | · · · · · · · · · · · · · · · · · · · | . ~ | |
| Name& Address | 100 S. Main, Ste. 505 | Well Total Dept | h 4630 | 150.48 1001 | |
| | Vichita, KS 67202-3738 | _ Conductor Pipe: | Conductor Pipe: Sizefeet | | |
| | , | Surface Casing: | \$1ze 8 5/8 | feet 284 | |
| Abandoned O | il WeilGas Weil | Input Well | SWD Well | D&AX | |
| | as hereinafter indicated | | | · | |
| | ntractor Abercrombie Drill | ing, Inc. | License N | umber 30684 | |
| Address | 150 N. Main, Ste. 801, Wichi | ta, KS 67202 | • | | |
| | plug at: Hour: 12:30 p.m.Day: | | | Year 19 95 | |
| Company to | | _ | | | |
| • | | | | | |
| | oposal received from Tony M | | | 216 262 1941 | |
| (company na | ae) Abercrombie | | (ph | one) 316-262-1841 | |
| (company na | Abercrombie fill hole with heavy mud and s | pot cement through dr | ill pipe | Anhydrite 2124-58' | |
| (company na were: to: lst plug at | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd | pot cement through dr | ill pipe | Anhydrite 2124-58' | |
| (company nawere: to stoplug at 3rd plug at | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th | pot cement through dr | ill pipe | Anhydrite 2124-58' | |
| (company nawere: to stoplug at 3rd plug at | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd | pot cement through dr | ill pipe | Anhydrite 2124-58' | |
| (company nawere: to stoplug at 3rd plug at 5th plug at | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th | pot cement through dr plug at 1350' with 8 plug at 300' with 40 | ill pipe | Anhydrite 2124-58' | |
| (company nawere: to stoplug at 3rd plug at 5th plug at | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx | pot cement through dr plug at 1350' with 8 plug at 300' with 40 | sill pipe and sx cement, | Anhydrite 2124-58' t, Durrant | |
| (company nawere: to lst plug at 3rd plug at 5th plug at 6th plug to | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx Plugging Pr | pot cement through drawing plug at 1350' with 8 plug at 300' with 40 cement. | sill pipe And Steve | Anhydrite 2124-58' t, Durrant ECHNICIAN) | |
| (company navere: to lst plug at 3rd plug at 5th plug at 6th plug to | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx Plugging Pr perations attended by Agent7: | plug at 1350' with 8 plug at 300' with 40 cement. cement. | steve | Anhydrite 2124-58' t, Durrant ECHNICIAN) None X | |
| (company nawere: to lst plug at 3rd plug at 5th plug at 6th plug to Plugging Oporations | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx Plugging Pr perations affended by Agent?: Completed: Hour: 5 p.m. Day | pot cement through drawing plug at 1350' with 8 plug at 300' with 40 cement. cement. Ali Part | steve | Anhydrite 2124-58' t, Durrant ECHNICIAN) None X | |
| (company nawers: to lst plug at 3rd plug at 5th plug at 6th plug to Plugging Operations ACTUAL PLUG | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx Plugging Pr perations affended by Agent?: Completed: Hour: 5 p.m. Day GGING REPORT 1st plug at 2150' | pot cement through drawing plug at 1350' with 8 plug at 300' with 40 cement. cement. Ali Part | steve | Anhydrite 2124-58' t, Durrant ECHNICIAN) None X | |
| (company nawere: to lst plug at 3rd plug at 5th plug at 6th plug to Plugging Operations ACTUAL PLUG | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx Plugging Pr perations affended by Agent?: Completed: Hour: 5 p.m. Day | pot cement through drawing plug at 1350' with 8 plug at 300' with 40 cement. cement. Ali Part | steve | Anhydrite 2124-58' t, Durrant ECHNICIAN) None X | |
| vere: to lst plug at 3rd plug at 5th plug at 6th plug to Plugging Op Operations ACTUAL PLUG 2nd plug at | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx Plugging Pr perations affended by Agent?: Completed: Hour: 5 p.m. Day GGING REPORT 1st plug at 2150' | pot cement through drawing plug at 1350' with 8 plug at 300' with 40 cement. cement. Ali Part | steve | Anhydrite 2124-58' t, Durrant ECHNICIAN) None X | |
| vere: to 1st plug at 3rd plug at 5th plug at 6th plug to Plugging Op Operations ACTUAL PLUG 2nd plug at 3rd plug at | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx Plugging Pr perations attended by Agent?: Completed: Hour: 5 p.m. Day GGING REPORT 1st plug at 2150' 1350' with 80 sx cement, | pot cement through drawing plug at 1350' with 8 plug at 300' with 40 cement. cement. Ali Part | steve | Anhydrite 2124-58' t, Durrant ECHNICIAN) None X | |
| vere: to 1st plug at 3rd plug at 5th plug at 6th plug to Plugging Op Operations ACTUAL PLUG 2nd plug at 3rd plug at 4th plug at | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx Plugging Pr Professions affended by Agent?: Completed: Hour: 5 p.m. Day GGING REPORT 1st plug at 2150' 1350' with 80 sx cement, 870' with 40 sx cement, | pot cement through drawing plug at 1350' with 8 plug at 300' with 40 cement. cement. Ali Part | sill pipe 430 sx cement, sx cement, Steve | Anhydrite 2124-58' t, Durrant ECHNICIAN) None X | |
| company navere: to lst plug at 3rd plug at 5th plug at 6th plug to 2rd plug at 3rd plug at 3rd plug at 5th plug at 5th plug at 6th plug at | Abercrombie fill hole with heavy mud and s 2150' with 50 sx cement, 2nd 870' with 40 sx cement, 4th 40-0' with 10 sx cement, circulate rathole with 15 sx Plugging Pr perations affended by Agent?: Completed: Hour: 5 p.m. Day GING REPORT 1st plug at 2150' 1350' with 80 sx cement, 870' with 40 sx cement, 300' with 40 sx cement, | pot cement through drag plug at 1350' with 8 plug at 300' with 40 cement. cement. AllPart with 50 sx cement, | Steve (TE | Durrant ECHNICIAN) None X Year:19 95 | |

(TECHNICIAN)