		1 050598	API NUMBER 15- 101-21	,176-0000	
	To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202				
			NW SE NE , SEC. 21	•	
				from S section line	
	TECHNICIAN'S PLUGGING REPORT		feet from E section line		
	Operator L	icense #5144	Lease Name Boomhower		
	Operator:	Mull Drilling Company, Inc.	County Lane	/50.90 4643 (Mississippi) feet	
	Name& Address	P. O. Box 2758	Well Total Depth	4643 (MISSISSIPPI)	
		Wichita, KS 67201	Conductor Pipe: Size	feet	
			Surface Casing: Size	8 5/8" feet 346	
	Abandoned	Oll WellGas Well	Input WellSWD	WellD&A	
	Other well as hereinafter indicated				
	Plugging Contractor Mallard Drilling Company License Number 5651				
	Address 405 Century Plaza, Wichita, KS 67202				
	Company to plug at: Hour: 7:00 am Day: 13 Month: August Year:1985				
	Plugging proposal received from Patty				
	(company	name) <u>Mallard</u>		(phone) 316-263-8218	
	were: to fill hole with heavy mud and spot cement through drill pipe Elevation N/A Anhydrite 2214-2240				
	1st plug at 2230' with 50 sx cement				
		at 1600' with 50 sx cement			
	3rd plug	at 780° with 50 sx cement			
	4th plug at 360' with 40 sx cement				
	solid bridge 5th plug hulls - plug at 40' Plugging Proposal Received by Richard W. Lacey				
	cement to surface with 10 sx cement.				
	7th plug Plugging	to circulate rat hole with 15 s Operations attended by Agent?:	x cement All Part	None X	
	Operations Completed: Hour: 9:50 am Day: 13 Month: August Year: 1985				
	ACTUAL PLUGGING REPORT 1st plug at 2230' with 50 sx cement, 2nd plug at 1600' with 50				
	sx cement, 3rd plug at 780' with 50 sx cement, 4th plug at 360' with 40 sx cement,				
	SA CEMENT	5th & 6th plugs - solid bridge - hulls - plug at 40' cement to surface with 10 sx			
	5th & 6th	plugs - solid bridge - hulls -	plug at 40' cement to	surface with 10 sx	
				surface with 10 sx	
		plugs - solid bridge - hulls - th plug to circulate rat hole w		surface with 10 sx	
				surface with 10 sx	
				surface with 10 sx	
	cement, 7	th plug to circulate rat hole w	ith 15 sx cement.	surface with 10 sx	
	cement, 7		ith 15 sx cement.		
V. C.	cement, 7	th plug to circulate rat hole w Used 60/40 Pozmix 6% gel by Hal	liburton. Is necessary, use BACK of		
	cement, 7	Used 60/40 Pozmix 6% gel by Hal (if additional description did not) observe this pluggings	ith 15 sx cement. liburton. Is necessary, use BACK of		