

CP 1

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM  
File One Copy

Lease Owner PURCELL MULL DRILLING CO. Address 6427 East Kellog, Wichita, Kansas  
(Applicant)

Lease (Farm Name) Schmidt Well No. 1

Well Location \_\_\_\_\_ Sec. 25 Twp. 30 Rge. (E) - (W) 12W

County Barber Field Name (if any) \_\_\_\_\_

Total Depth 4460' Oil Gas Dry Hole Dry

Was well log filed with application? no If not, explain: Will Follow

Date and hour plugging is desired to begin 4-20-55

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner J. O. Forbes

d/b/a Forbes Casing Pulling Co. Address Box 221, Great Bend, Kansas

Plugging Contractor Forbes Casing Pulling Co.

Plugging Contractor's License No. 49

Address Box 221, Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to \_\_\_\_\_

Parcell Mull Drilling Co., Inc. Address 6427 East Kellog, Wichita, Kansas

and payment will be guaranteed by applicant.

J. O. Forbes

Applicant or Acting Agent

Date 4-20-55

**RECEIVED**  
STATE CORPORATION COMMISSION  
APR 22 1955  
CONSERVATION DIVISION  
Wichita, Kansas

**PLUGGING**  
FILE SEC 25T.30R.12W  
BOOK PAGE 114 LINE 5



STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

~~XXXXXXXXXXXXXXXXXXXX~~  
WICHITA 2, KANSAS

211 N. Broadway

April 22, 1955

Well No.	1
Lease	Schmidt
Description	25-30-12W
County	Barber
File No.	114-5

Purcell-Hull Drilling Co.  
6427 E. Kellogg  
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. H. A. Rivas, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

BY:

*J. P. Roberts*  
J. P. ROBERTS

cc: District Plugging Supervisor