KANSAS STATE CORFCHATION COMMISSION

WELL PLUGGING SUPERVISOR'S REPORT

TO: Jewel M. Ogden, Director 500 Insurance Building 212 North Market dichita 2. Kansas

| 3 | / |
|---|---|
| | |
| | |

| nonizou zy nanizo | | | | | |
|--|---|---|---|--|---------------------------|
| File No. | Location:CE/2 | E/2 SW/4 | | | |
| County: Barber | Sec. 10 | | Rge. <u>10</u> | (E)_ | _(h) <u>X</u> |
| Name of Field or Pool: | ** · · · · · · · · · · · · · · · · · · | | Fotal Depth: | 4450 | |
| I have this date completed | supervision of pluggi | ng of: | | | |
| Nell No. 1 | Lease Dohm- Smith | | | | |
| Operator's Full Name Nat | | | | | |
| Complete Address: 305 R | | | | | |
| Plugging Contractor: Gab | | | | | |
| Address: Great Bend, | | | | | |
| Candoned Oil WellGa | | | | | |
| If well is a rotary drille | | | | | |
| If yes how long | | | | • | |
| | | | | | |
| | | | | | |
| peration Completed: Hour | | | | | |
| · | | | | | |
| The above well was plugged | as follows: | | | | |
| The above well was plugged 2008 of 8 5/8" surface plug with 1/3 sack bul | pipe. Heavy dril. | ent placed | through d | rill p | ipė |
| 2008 of 8.5/8 surface plug with $1/3$ sack bul | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing | ent placed | through d | rill p | ipė |
| 2008 of 8 5/8" surface olug with 1/3 sack bull to 3 | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing | ent placed | through d | rill p | ipė |
| 2008 of 8 5/8" surface alug with 1/3 sack bul at 190 feet. Mud to 3 sack cement to surface | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing | ent placed | through d | rill p | ipė |
| 2008 of 8 5/8" surface riug with 1/3 sack bull to 190 feet. Mud to 3 ack cement to surface hereby certify that the a | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing p .AX above well was plugged | ent placed | through d | rill p | ipe O |
| 2008 of 8 5/8" surface alug with 1/3 sack bulk to 3 sack cement to surface hereby certify that the a | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing parts. 2) - 1958 above well was plugged all was being plugged. | ent placed plug, 1/3 as herein s | through d | rill p and l at I wa | ipe O |
| 2008 of 8 5/8" surface alug with 1/3 sack bulk to 190 feet. Mud to 3 ack cement to surface above well to the above well | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing .AX above well was plugged. Signed: | ent placed plug, 1/3 as herein s | through d sack hulls tated and the | rill p and 1 at I wa | ipe 0 |
| hereby state that I was received the best of my knowledge | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing .AX above well was plugged ll was being plugged. Signed: and present while the act and belief it was plu | ent placed plug, 1/3 as herein s Well F | through d sack hulls tated and th lugging Supe as being plu | at I wa | ipe 0 |
| hereby state that I was received the best of my knowledge or my not being present is | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing .AX above well was plugged ll was being plugged. Signed: not present while the act and belief it was plugged as follows: | as herein s Well F | through d sack hulls tated and the lugging Supe as being plue | at I was | owever, |
| hereby certify that the are the best of my knowledge or my not being present is | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing .AX above well was plugged ll was being plugged. Signed: not present while the act and belief it was plugged as follows: | ent placed plug, 1/3 as herein s Well F above well w agged as her or pluggin | through d sack hulls tated and the lugging Supe as being plu ein stated g orders m | at I was | ipe 0 |
| cool pushed Jack Gabber | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing .AX above well was plugged ll was being plugged. Signed: not present while the act and belief it was plugged e and belief it was plugged that as follows: rt called asking for the act as it would be it. | as herein s Well F above well wagged as here or pluggin | through d sack hulls tated and th lugging Supe as being plu ein stated. g orders m l plugging | at I was | ipe 0 owever, account of |
| hereby state that I was received the best of my knowledge or my not being present is col pushed Jack Gabbe. 5 March 1958. Inasmuthat Mr. Gabbert call for Gabbert failed to | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing .MI above well was plugged ll was being plugged. Signed: not present while the act and belief it was plugged eas follows: rt called asking for the sact as it would be in the | as herein s Well F above well w legged as her or pluggin nours unti | through d sack hulls tated and the lugging Supe as being plu ein stated. g orders m l plugging k down dri plugged as | at I was rvisor gged, he full orning I ask ll pip | of ed |
| hereby certify that the active with 1/3 sack bull ack cement to surface. hereby certify that the active well ack the best of my knowledge or my not being present is cool pushed Jack Gabber 5 March 1958. Inasmuthat Mr. Gabbert call fr. Gabbert failed to eviewed: | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing .MI above well was plugged ll was being plugged. Signed: not present while the act and belief it was plugged eas follows: rt called asking for the sact as it would be in the | as herein s Well F above well w legged as her or pluggin nours unti | through d sack hulls tated and th lugging Supe as being plue ein stated. g orders m l plugging k down dri plugging Supe | at I was rvisor gged, he full orning I ask ll pip above | of ed |
| hereby state that I was received the best of my knowledge or my not being present is march 1958. Inasmuthat Mr. Gabbert call fr. Gabbert failed to | pipe. Heavy dril. ls and 20 sack ceme 5' with cementing .MI above well was plugged ll was being plugged. Signed: not present while the act and belief it was plugged eas follows: rt called asking for the sact as it would be in the | as herein s Well F above well wagged as her or pluggin nours unti | through d sack hulls tated and the lugging Supe as being plu ein stated. g orders m l plugging k down dri plugged as | at I was at I was rvisor gged, he full orning I ask Il pip above | owever, |