<i>(</i>)					001	?
$\mathcal{A}_{\mathcal{V}^{\mathcal{A}}}$	1 050798	-			249	7 D
၄ To:			API NUMBER 15-	135-23.02	1 1. ወ ური	
STATE CORP	PORATION COMMISSION ION DIVISION - PLUGGING	SECTION AP	oprox. NE NWsec			21 / X X
200 COLORA	DO DERBY BUILDING	32311011				
	(ANSAS 67202		4000	feet from		
TECHNICIAN	I'S PLUGGING REPORT			feet from		
•	icense # 9746		Lease Name <u>Pemb</u> e			4
Operator: Name& Address	Wilkar Oil Company		County Nes	ss		146,12
	10707 Norwalk Blvd.	·	Well Total Dept	h 4496 Miss	issippi	feet
	Santa Fe Springs, C	CA 90670	Conductor Pipe:	Size	feet_	
		·	Surface Casing:	\$1ze <u>8 5/8</u>	_feet	260
Abandoned	Oll Weil Gas	Well _	input Well	SWD Well	D	A.A. X
	l as hereinafter indica					
_	Contractor Red Tiger Dr				has	5302
	1720 Kansas State H			-		
						96
Company to	o plug at: Hour: 5:00 am			L 11	Year:19_	
	<u> </u>	Ken	nneth Lyle			
	proposal received from_	KCI				
	name) Red Tiger	KCI		(phon	e) 316-26	63-1201
(company r	name) Red Tiger fill hole with heavy mu			Ele	vation 22	264'
(company r	name) Red Tiger	ud and spot c		Ele	vation 22	264'
(company r	fill hole with heavy mu	ud and spot c		Ele	vation 22	264'
(company rwere: to lst plug	fill hole with heavy mu / 588 at 1988 with 50 sx cen at 750 with 75 sx cen	ud and spot c nent nent		Ele	vation 22	264'
(company rewere: to lst plug 2nd plug 3rd plug	Red Tiger fill hole with heavy mu 7588 at 1968 with 50 sx cen at 750 with 75 sx cen at 290° with 40 sx cen	ud and spot conent	cement through dr	Ele	vation 22	264'
(company rewere: to lst plug 2nd plug 4th plug	fill hole with heavy mu 1588 at 1988 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface wi	ud and spot conent ment ment	cement through dr	Elevill pipe Anh	vation 22 ydrite 1:	264'
(company rewere: to lst plug 2nd plug 4th plug	Red Tiger fill hole with heavy mu 7588 at 1968 with 50 sx cen at 750 with 75 sx cen at 290° with 40 sx cen	ud and spot conent ment ment	cement through dr	ill pipe Anh	vation 22 ydrite 1:	264'
(company reserved to lst plug 2nd plug 4th plug 5th plug	fill hole with heavy mu 1588 at 1988 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface with to circulate rat hole	ud and spot conent ment ith 10 sx cen with 15 sx cen gging Propos	ment cement through dr	Dan Goodrow	vation 22 ydrite 1:	264'
(company of were: to lst plug 2nd plug 3rd plug 4th plug 5th plug	fill hole with heavy mu / 5 % at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface with to circulate rat hole Plu Operations attended by	nent ment ith 10 sx cem with 15 sx cen gging Propos Agent?: All	ment cement through dr	Dan Goodrow	vation 22 ydrite 15	264' 580-90'
(company of were: to lst plug 2nd plug 3rd plug 4th plug 5th plug Plugging (Operations	fill hole with heavy mu / 3 88 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface wi to circulate rat hole Plu Operations attended by s Completed: Hour: 11:	nent ment ith 10 sx cem with 15 sx c igging Propos Agent?: All :00 ampay: 20	ment cement through dri ment cement al Received by	Dan Goodrow (TECH	vation 22 ydrite 15 HNICIAN) Hone Year:19	86
vere: to 1st plug 2nd plug 3rd plug 4th plug 5th plug Plugging (Operations ACTUAL PL	fill hole with heavy must be at 1988 with 50 sx cent at 750 with 75 sx cent at 290° with 40 sx cent from 40° to surface with to circulate rat hole Plus Completed: Hour: 11: UGGING REPORT 1st plug	ment ment ith 10 sx cem with 15 sx cen gging Propos Agent?: All :00 ampay: 20 at 1888' with	ment cement through dri	Dan Goodrow (TECH	vation 22 ydrite 15 inician) inician) inician) inician) inician) inician)	86 h 75 sx
vere: to 1st plug 2nd plug 3rd plug 4th plug 5th plug Plugging (Operations ACTUAL PL	fill hole with heavy mu / 3 88 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface wi to circulate rat hole Plu Operations attended by s Completed: Hour: 11:	ment ment ith 10 sx cem with 15 sx cen gging Propos Agent?: All :00 ampay: 20 at 1888' with	ment cement through dri	Dan Goodrow (TECH	vation 22 ydrite 15 inician) inician) inician) inician) inician) inician)	86 h 75 sx
company of were: to lst plug 2nd plug 2nd plug 4th plug 5th plug 5th plug 60 perations ACTUAL PLU cement,	fill hole with heavy must be at 1988 with 50 sx cent at 750 with 75 sx cent at 290° with 40 sx cent from 40° to surface with to circulate rat hole Plus Completed: Hour: 11: UGGING REPORT 1st plug	ment ment ith 10 sx cem with 15 sx ce igging Propos Agent?: All :00 ampay: 20 at 1888' with	nent cement through drived ment cement cal Received by	Dan Goodrow (TECH	vation 22 ydrite 15 inician) inician) inician) inician) inician) inician)	86 h 75 sx
company of were: to lst plug 2nd plug 2nd plug 4th plug 5th plug 5th plug 60 perations ACTUAL PLU cement,	fill hole with heavy mu / 3 88 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40' to surface wi to circulate rat hole Plu Operations attended by Completed: Hour: 11: UGGING REPORT 1st plug 3rd plug at 290' with 40	ment ment ith 10 sx cem with 15 sx ce igging Propos Agent?: All :00 ampay: 20 at 1888' with	nent cement through drived ment cement cal Received by	Dan Goodrow (TECH	Varion 22 ydrite 15 HNICIAN) Hone Year:19 750' with e with 10	86 h 75 sx
company of were: to lst plug 2nd plug 2nd plug 4th plug 5th plug 5th plug 60peration: ACTUAL PLU cement, cement,	fill hole with heavy mu / 3 88 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40' to surface wi to circulate rat hole Plu Operations attended by Completed: Hour: 11: UGGING REPORT 1st plug 3rd plug at 290' with 40	nent ment ith 10 sx cem with 15 sx ce igging Propos Agent?: All :00 ambay: 20 at 1888' with 40 sx cement, rat hole with	ment cement cement cal Received by	Dan Goodrow (TECH	Varion 22 ydrite 15 HNICIAN) Hone Year:19 750' with e with 10	86 h 75 sx
company of were: to lst plug 2nd plug 2nd plug 4th plug 5th plug 5th plug 60peration: ACTUAL PLU cement, cement,	fill hole with heavy mu / 3 8 8 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface wi to circulate rat hole Plu Operations attended by Completed: Hour: 11: UGGING REPORT 1st plug 3rd plug at 290 with 4 5th plug to circulate rat	nent ment ith 10 sx cem with 15 sx ce igging Propos Agent?: All :00 ambay: 20 at 1888' with 40 sx cement, rat hole with	ment cement cement cal Received by	Dan Goodrow (TECH	Varion 22 ydrite 15 HNICIAN) Hone Year:19 750' with e with 10	86 h 75 sx
vere: to lst plug 2nd plug 3rd plug 4th plug 5th plug Operation: ACTUAL PLU cement, dement.	fill hole with heavy mu / 3 8 8 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface wi to circulate rat hole Plu Operations attended by Completed: Hour: 11: UGGING REPORT 1st plug 3rd plug at 290 with 4 5th plug to circulate rat 1: 42 Viscosity 9.9 ppg	and spot coment ment ith 10 sx cem with 15 sx coment, gging Propos Agent?: All :00 ambay: 20 at 1888' with 40 sx cement, rat hole with g Tagged 1st	ment cement cal Received by X Part O Month: A th 50 sx cement, 4th plug from 4	Dan Goodrow (TECH	Vation 22 ydrite 15 INICIAN) Hone Year: 19 750' with e with 10 CONSER	86 h 75 sx
vere: to lst plug 2nd plug 3rd plug 4th plug 5th plug Operation: ACTUAL PLU cement, dement.	fill hole with heavy mu / 3 8 8 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface wi to circulate rat hole Plu Operations attended by Completed: Hour: 11: UGGING REPORT 1st plug 3rd plug at 290 with 4 5th plug to circulate rat	and spot coment ment ith 10 sx cem with 15 sx coment, gging Propos Agent?: All :00 ambay: 20 at 1888' with 40 sx cement, rat hole with g Tagged 1st	ment cement cal Received by X Part O Month: A th 50 sx cement, 4th plug from 4	Dan Goodrow (TECH	Vation 22 ydrite 15 INICIAN) Hone Year: 19 750' with e with 10 CONSER	86 h 75 sx
vere: to lst plug 2nd plug 3rd plug 4th plug 5th plug Operation: ACTUAL PLU cement, dement.	fill hole with heavy mu / 3 8 8 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface wi to circulate rat hole Plu Operations attended by Completed: Hour: 11: UGGING REPORT 1st plug 3rd plug at 290 with 4 5th plug to circulate rat 1: 42 Viscosity 9.9 ppg	and spot coment ment ith 10 sx cem with 15 sx com gging Propos Agent?: Ali :00 ambay: 20 at 1888' with 40 sx cement, rat hole with g Tagged 1st cription is n	ment cement through drived ment cement al Received by	Dan Goodrow (TECH pril 2nd plug at 0' to surface	Vation 22 ydrite 15 INICIAN) Hone Year: 19 750' with e with 10 CONSER	86 h 75 sx
Vere: to 1st plug 2nd plug 2nd plug 3rd plug 4th plug 5th plug Operations ACTUAL PLU cement, Cement. Mud Info	fill hole with heavy mu / 3 88 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40' to surface wi to circulate rat hole Plu Operations attended by s Completed: Hour: 11: UGGING REPORT 1st plug 3rd plug at 290' with 4 5th plug to circulate rat a: 42 Viscosity 9.9 ppg Used 60/40 Pozmix 6% gen (If additional descriptions)	and spot coment ment ith 10 sx cem with 15 sx com gging Propos Agent?: Ali :00 ambay: 20 at 1888' with 40 sx cement, rat hole with g Tagged 1st cription is n	ment cement cal Received by X Part O Month: A th 50 sx cement, 4th plug from 4	Dan Goodrow (TECH pril 2nd plug at 0' to surface	Vation 22 ydrite 15 INICIAN) Hone Year: 19 750' with e with 10 CONSER	86 h 75 sx
vere: to lst plug 2nd plug 3rd plug 4th plug 5th plug Operation: ACTUAL PLU cement, dement.	fill hole with heavy mu / 3 88 at 1968 with 50 sx cen at 750 with 75 sx cen at 290 with 40 sx cen from 40 to surface wi to circulate rat hole Plu Operations attended by S Completed: Hour: 11: UGGING REPORT 1st plug 3rd plug at 290 with 40 5th plug to circulate rat 1: 42 Viscosity 9.9 ppg Used 60/40 Pozmix 6% gen (If additional descriptions) 9 1986	and spot coment ment ith 10 sx cem with 15 sx com gging Propos Agent?: Ali :00 ambay: 20 at 1888' with 40 sx cement, rat hole with g Tagged 1st cription is n	ment cement through drived ment cement al Received by	Dan Goodrow (TECH pril 2nd plug at 0' to surface	Vation 22 ydrite 15 INICIAN) Hone Year: 19 750' with e with 10 CONSER	86 h 75 sx