

CR1

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner National Cooperative Refinery Association Address 305 Rule Building, Wichita, Kansas
(Applicant)

Lease (Farm Name) SKINNER "E" Well No. 1

Well Location SE NW NE Sec. 12 Twp. 32S Rge. 15W (E) (W)

County Barber Field Name (if any) _____

Total Depth 5050 Oil _____ Gas _____ Dry Hole X

Was well log filed with application? No If not, explain: Will File When

Available from Contractor

Date and hour plugging is desired to begin At Once

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner Lawrence Detmer

Address Box 6, Great Bend, Kansas

Plugging Contractor Capitt Drilling, Inc.

Plugging Contractor's License No. _____

Address 814-16 Union Center Building, Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to NCRA

Address 305 Rule Building, Wichita, Kansas

and payment will be guaranteed by applicant.

C.R. Sears

Applicant or Acting Agent
C.R. Sears

RECEIVED
STATE CORPORATION COMMISSION

Date April 29, 1957

PLUGGING
FILE SEC. 12 T. 32 R. 15W
BOOK PAGE 9 LINE 12

APR 30 1957
4-30-57
CONSERVATION DIVISION
Wichita, Kansas



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS
April 29, 1957

Well No. 1
Lease Skinner "B"
Description SE 1/4 12-32-15
County Barber
File No. 9-12

National Cooperative Refinery Ass'n.
305 Rule Building
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY S. S. Greider
S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor