学员

KANSAS

Form CP-3 Rev. 6-4-68

STATE CORPORATION COMMISSION
CONSERVATION DIVISION AGENT'S REPORT

J. Lewis Brock
Administrator
P. O. Box 17027
Wichita, Kansas 67217

RECEIVED STATE CORPORATION COMMISSION

FER 1 19/3
2-1-7-3
CONSERVATION DIVISION
Wichita, Kansas

Complete Address 816 Union Center Bldg Wichita, KS Lease Name Mills B well No. 1 Location NW/NE/SE Sec. 8 Twp. 318 Rge. 14 (E) (W) W County Barber Total Depth 4480 Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated	Operator's Full Name_	Kedco Corporation	·	Wichita, Kansas
Location NW/NE/SE Sec. 8 Twp. 318 Rge. 14 (E) (W) W County Barber Total Depth 4480 Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated	Complete Address	816 Union Center Bldg	Wichita, KS	
County Barber Total Depth 4480 Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated	Lease Name Mills	В	Well No. 1	
Abandoned Oil Well Gas Well Input Well SWD Well D & A X Other well as hereafter indicated	Location NW/NE/S	BE .	_Sec8_Twp31s _{Rg}	ge. 14(E) (W) W
Abandoned Oil Well Gas Well Input Well SWD Well D & A X Other well as hereafter indicated	County Barber		Total Depth	4480
	Abandoned Oil Well			
H-22-12 Bu2 - G - T	Other well as hereaft	er indicated		
Plugging Contractor Hellar Drlg Co Inc	Plugging Contractor	Hellar Drlg Co Inc		
Address 339 Union Center Wichita, KS License No.	Address 339 Union	Center Wichita, KS	License N	io
Operation Completed: Hour 11:30 AM Day 30 Month 1 Year 1973	Operation Completed:	Hour 11:30 AM Day 30	Month 1	Year 1973
The above well was plugged as follows:	The above well was pl	ugged as follows:		
40 ft 16" conduction pipe with 200 sacks, cement. 740 ft 8 5/8	40 ft 16" conduct	ion pipe with 200 sack	s, cement. 740	ft 8 5/8
surface cemented with 200 sacks, basket, 4 yds chat. Fill hole to	surface cemented	with 200 sacks, basket	, 4 yds chat.	Fill hole to
500 ft, plug, a sack hulls, 40 sacks cement. Mud to 40 ft, plug,	500 ft, plug, 1 :	sack hulls, 40 sacks ce	ement. Mud to 4	O ft, plug,
be sack hulls, 15 sacks cement to surface. 2 sacks cement in rat hole	½ sack hulls, 15	sacks cement to surface	e. 2 sacks cem	ent in rat hole.
I hereby certify that the above well was plugged as herein stated.	I hereby certify that	the above well was plugged	as herein stated.	
INVOICED signed: Manual Billion	1 01 14 0 5 4	^ P* P^		Will to
Well Plugging Supervigor	DATE 2/	1/23		ng Supervisor
INV. NO. 6932-W	INV. NO6	932-W		