KCC OIL/GAS REGULATORY OFFICE

DATE12/16/97	New Situation
OPERATOR American Warrior, Inc. # 4058	12-22-97 [] Response to Request RECEIVED NEC Follow-up
NAME P.O. Box 399	KANSAS CURPSE OF LOCATION SEC 33 ,T 18 S.P. 21 W
& ADDRESS Garden City, KS 67846	LEASE Ryersee 2: 14 Well # 2-33
PHONE NO. OPER. 785-398-2270 OTHER	COUNTY_Ness API#15-135-24,027-000
REASON FOR INVESTIGATION: Alternate II cement	
	INSPECTION
	SPE
PROBLEM:	ļ ·
	LEASE
PERSON(S) CONTACTED:	
FINDINGS: $5\frac{1}{2}$ " casing set in the Mississippi. 8 tool set at 1383. Couldn't open the port coll	
5½" casing at 1365. Pumped 110 sx Halliburton	L.
and it stopped. Did not circulate cement. To	
call the district office.	S contract to get a cement top and
12/17/97 Found cement top at 390' with possib	le strings up to 170°. Pressured 8 5/8" X 5½"
annulus to 600#. Couldn't pump.	11essureu 0 3/0 A 32
ded de coon. Couldn't pump.	
ACTION/RECOMMENDATIONS: The Alternate II co	photos taken:
TO TONY MEDITINE TONG	
	x I III III X
Patain 1 conv laint District Conv	SACHER
Retain 1 copy Joint District Office Send 1 copy Conservation Division	By Richard W. Lacey
	12/17/97