KCC OIL/GAS REGULATORY OFFICE -- -- --

DATE 5/13/97	•	[x] New Situation	
OPERATOR McCoy Petroleum Corp. # 5003		[] Response to Red [] Follow-up	quest
NAME 3017 N. Cypress St.	App. LOCATION E/2 NW	,SEC 13 ,T 20 S.R	25 ¥
& ADDRESS Wichita, KS 67226-4003	LEASE Ring A	Well # 1-13	
PHONE NO. Steve O'Neill OPER. 316-636-2737 OTHER	COUNTY Ness API	#15-135-23,994 -	2
REASON FOR INVESTIGATION: Alternate II ceme	nting completion		Z
		,	INSPECTION
			NSPB
PROBLEM:			!
			LEASE
PERSON(S) CONTACTED:			
			•
FINDINGS: TD @ 4450', Open hole completion, 8	5/8" @ 641' w/325 sx	cement, 15½# 5½" at	4441 [†] ∵₩/
Port collar at 1656'. Used 250 sx 65/35 Pozmi	x 6% gel ¼# floseal.	. 125 sx cemen	t -[.
Cement did not circulate. Had circulation for	about half of mixin	g, then lost returns.	N A IN
Ran temperature survey on 5/14/97. Cement was	at 990'. Will comple	te when well is	
completed.		-	
5/19/97 Finished cement job that didn't ci	rculate. Cement was	at 950°, Pumped 125 s	x
common 3% cc cement and 75 sx 65/3	5 Pozmix 6% gel down	backside. Pressure	went
from 600-900#. Fell back to 400#,	then went back to 9	00# at the end Shut	in
with 500#.	,	1 S C	7
		7 7 C7 /	
		photos taken: 1 ? 6	
ACTION/RECOMMENDATIONS: Alternate II cementing		5 3	X REPORT
			1
			FIELD
Retain 1 copy Joint District Office	Ву	Mike Maier	X
Send 1 copy Conservation Division		5/13/97	K
		5/19/97	