KCC OIL/GAS REGULATORY OFFICE ...

DATE 8/7/97	[X] New Situation	
OPERATOR Pickrell Drilling Co., Inc. # 5123	[] Response to Red [] Follow-up	quest
NAME 110 N. Market, Ste. 205	20' N & 70' E of LOCATION:/2 E/2 NE,SEC 25,T 19 S,P	X _E X 22 ₩
& ADDRESS Wichita, KS 67202	LEASE Borger Well # 3	
PHONE NO. OPER. 316-262-8427 OTHER	:COUNTYNess_API#15-135-23,	,998 -000 0
REASON FOR INVESTIGATION: Alternate II cementi	ing	z
		INSPECT 10N
		NSPB
PROBLEM:		LEASE I
		E
PERSON(S) CONTACTED:		
FINDINGS: TD @ 4349', 5½" at 4340' with 125		
	sx in pit, pumped 300 sx 65/35 Pozmix	
6% gel, 戈# floseal. Also put 15 sx o	and the second s	COMPLAINT
	<u>`</u>	
	L2 CENT	
ACTION/RECOMMENDATIONS:Alternate II cementing	photos taken: ng completed.	REPORT
		Tero
		—[L.
Retain 1 copy Joint District Office	By Mike Maier	
Send 1 copy Conservation Division	8/7/97	