

STATE OF KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION &OO BITTING BUILDING WICHITA, KANSAS

 \mathcal{N}^{\setminus}

WELL PLUCGING APPLICATION FORM File One Copy

Lease Cwner Magnolia	Petroleum Company	Address Box 7	70 - Grea	at Bend, Kansas
(Applicant) Lease (Farm Name)	Jefferson Long			Well No. 1
Well Location	SW NW SW	Sec. 13 Twp. 31S Rge	- 13 XXX	-(W)
County	Barber	Field Name (if	any)	Nurse
Total Depth_	3725 PB: 3687	Oil Gas	X Dry	Hole
Was well log filed wi	th application? No	. If not,	explain	*
To be furnished at tim	e of plugging			
Date and hour plugging	is desired to begin	Immediatel;	У	
Plugging of the well will be done in accordance with the Rules and Regulations				
of the State Corporation Commission, or with the approval of the following				
exceptions: Explain fully and exceptions desired.				
(Use an additional she	et if necessary)			
Name of the person on		•		
Foreman,		Address Box 31, 1	Harper, K	ansas .
Foreman, Name of Plugging Contr	actor ACE PIPE I	PULLING COMPANY	STATE	MISS. LINES REGISSION
Address	2905 16ta	n. Great Bend Kans	222	APR 27 1956
Invoice covering asses	smen. for plugging	this well should be	sent c? %	SERVATION DIVISION
Mr. R. C. Brannin, Di	st. Sup't.	Address Box 770	- Great H	Bend, Kansas
and payment will be gu	aranteed by applican	nt.		
		Applicant	San or Actin	ng Agent
PLUG	GING	Date Apri	il 26, 19	956



STATE OF KANSAS

STATE CORPORATION COMMISSION CONSERVATION DIVISION

211 NORTH BROADWAY WICHITA, KANSAS

April 27, 1956

Well No.

1

Lease

Jefferson Long

Description

SW NW SW 13-31-13W

County

Barber

File No.

57-17

Magnolia Petroleum Company Box 770 Great Bend, Kansas

Centlegens

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 8, Fratt, Kansas.

STATE CORPORATION COMMISSION CONSERVATION DIVISION

S. S. Greider

WELL PLUGGING SUPERVISOR

cc:

District Plugging Supervisor