3rd plug at 40' with 10 sx cement, 4th plug to circulate rathole with 15 sx cement.

Plugging Operations attended by Agent?: All______Part Operations Completed: Hour: 3:15 a.m. Day: 2 Month:

ACTUAL PLUGGING REPORT 1st plug at 600' with 50 sx cement.

2nd plug at 320' with 40 sx cement,

3rd plug at 40' with 10 sx cement,

4th plug to circulate rathole with 15 sx cement.

Remarks: Used 60/40 Pozmix 6% gel by Western.

(If additional description is necessary, use BACK of this form.)

MANY Dold Got Coserve this plugging.

My. No. _25

To:

Name&

Address

Signed

CONSERVATION DIVISION Wichita, Kansas