STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM File One Copy

(Applicant) Lease (Farm Name) Stephenson	Address P. O. Drawer 791 - Ponca City. Okla Well No. 1
		Sec. 28 Twp. 31SRge. 11 (ID) (W)
		Field Name (if any)
		Gas Dry Hole X
	4	Yes If not, explain:
Date and hour plu	agging is desired to	begin 8-14-56 - 2:00 P.M.
Plugging of the v	well will be done in	accordance with the Rules and Regulations
of the State Corp	poration Commission.	1
Name of the perso	on on the lease in o	charge of well for owner Melvin Endicott
	····	Address Box 791 - Ponca City, Oklahoma
Plugging Contract	tor L. C. Smithe	erman Drilling Company
Plugging Contract	tor's License No	244
	7 - Augusta, Kansas	**************************************
Address Box 627	assessment for plus	gging this well should be sent to
Address Box 627	assessment for plus	aging this well should be sent to
Address Box 627 Invoice covering Parker Petroleur	assessment for plus	Address Box 791 - Ponca City (1) home
Address Box 627 Invoice covering Parker Petroleur	assessment for plug	Address Box 791 - Ponca City (k1 home)
Address Box 627 Invoice covering Parker Petroleur	assessment for plug	aging this well should be sent to

PLUGGING
FILE SEC 28 T 31 R 11W
BOOK PAGE 90 LI E 35

Date August 16, 1956

 \mathscr{K}

15-007-00240-0000



STATE OF KANSAS

STATE CORPORATION COMMISSION

CONSERVATION DIVISION 211 NORTH BROADWAY WICHITA, KANSAS

August 16, 1956

Well No.

1

Lease

Stophonoca

Description

se we se 28-11-11e

County

File No.

90-35

Perior Petroleum Co., Inc. Por 791 Pones City, Oklahoum

Centlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 3, Pratt, Kenses.

STATE CORPORATION COMMISSION CONSERVATION DIVISION

By

S. S. Greider

WELL PLUGGING SUPERVISOR

cc:

District Plugging Supervisor