STATE OF KANSAS STATE CORPORATION COMMISSION

Form CP-4

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission

WELL PLUGGING RECORD

212 No. Market Wichita, Kansas		Barber					
NORTH		E/CNWKSWK" o					
	Lease Owner	Solar Nucko	oll co.	· · · · · · · · · · · · · · · · · · ·	,		#),
		Box					
	4	Vell (completed a					
	Data well com	pleted	B On, Gas of I	Jry Hole)			10
i	b	plugging filed					
		plugging approve					
	Plugging comm	renced	5.	-3-67			19
1	Plugging comp	leted	-5	-6-67			.19
		ndonment of well					
	If a producing	well is abandone	d, date of last	production			_19
		n obtained from			r its agents be	fore plugging	was com
Locate well correctly on above Section Plat	menced?						
laine of Conservation Agent who sup	pervised plugging of th	is well	Arch	ie Elving			-
roducing formation			Bottom_		Total Depth of	of Well_4330	Fee
how depth and thickness of all wate	r, oil and gas formatio	DS.					
OIL, GAS OR WATER RECOR	DS					CASING RE	CORD
							
FORMATION	CONTENT	FROM	TO	SIZE	NI TUG	PULLED	· · · · · · · · · · · · · · · · · · ·
. ,				5 1/2" 8 5/8"	4323' 150'	3071.2	<u> </u>
				0.5/0	150		
	 		 				
Made bottom hole dump bailer.	plug back with	sand to 35	50', mixe	d and ran	5 sacks	cement th	ru
Made bottom hole	plug back with	sand to 35	50', mixe	d and ran	5 sacks 7 joints.	cement th	ru
Made bottom hole dump bailer. Circulated hole a	plug back with	sand to 35	50', mixe	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th	ru
Made bottom hole dump bailer. Circulated hole a	plug back with	sand to 35	50', mixe	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th Squeeze	ru
Made bottom hole dump bailer. Circulated hole a	plug back with	sand to 35	50', mixe	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th	ru
Made bottom hole dump bailer. Circulated hole a	plug back with	sand to 35	50', mixe	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th Squeeze	ru
Made hottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with	sand to 35 O hbls. rot sacks ceemn	50', mixed ary mud. twith 2%	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th Squeeze	ru
Made hottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100	sand to 35 O hbls. rot sacks ceemn	50', mixed ary mud. twith 2%	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th Squeeze	ru
Made hottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100	sand to 35 O hbls. rot sacks ceemn	50', mixed ary mud. twith 2%	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th Squeeze	ru
Made hottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100	sand to 35 O hbls. rot sacks ceemn	50', mixed ary mud. twith 2%	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th Squeeze	ru
Made bottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100	sand to 35 O hbls. rot sacks ceemn	50', mixed ary mud. twith 2%	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th Squeeze	ru
Made bottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100	sand to 35 O hbls. rot sacks ceemn	50', mixed ary mud. twith 2%	d and ran Pulled 3 gel.	5 sacks 7 joints.	cement th Squeeze	ru
Made bottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100	sand to 35 0 bbls, rot sacks ceemn	50', mixe ary mud. t with 2%	d and ran Pulled 3 gel. Shift	5 sacks 7 joints.	cement th Squeeze	ru
Made bottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100	sand to 35 0 bbls, rot sacks ceemn	50', mixe ary mud. t with 2%	d and ran Pulled 3 gel. Sinte (5 sacks 7 joints. 7 joints. WAY 9 S-9-6 SERVATION Wichits, Ka	cement th Squeeze	ru
Made bottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100	sand to 35 0 bbls, rot sacks ceemn	50', mixed ary mud. twith 2% with 2% ary mud. twith 2% are	d and ran Pulled 3 gel. Sinte (5 sacks 7 joints. 7 joints. WAY 9 S-9-6 SERVATION Wichits, Ka	cement th Squeeze	ru
Made bottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100 (If addition Southwest Ca	sand to 35 0 bbls, rot sacks ceemn	50', mixed ary mud. twith 2% with 2% ary mud. twith 2% are	d and ran Pulled 3 gel. Sinte (5 sacks 7 joints. 7 joints. WAY 9 S-9-6 SERVATION Wichits, Ka	cement th Squeeze	ru
Made bottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100 (Haddition Southwest Ca Box 364, Gre	sand to 35 0 bbls, rot sacks ceemn aldescription is necessing Pullin at Bend, Ka	50', mixed ary mud. twith 2% twith 2% ary mud. twith 2% are mud. t	d and ran Pulled 3 gel. Single (5 sacks 7 joints. 7 joints. MAY 9 S-9-CONTINUM WICHIE, Ko	cement th Squeeze	ru
Made bottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100 (If additional Southwest Care Box 364, Green, CO)	sand to 35 0 bbls. rot sacks ceemn aldescription is necessing Pullin at Bend, Ka	50', mixed ary mud. twith 2% with 2% ary mud. twith 2% ary mud. The with 2% are with 2%	d and ran Pulled 3 gel. Shile (5 sacks 7 joints. 7 joints. Wichits, Ko	cement th Squeeze COMMISSION 1967 DIVISION nees	ru d
Made bottom hole dump bailer. Circulated hole a hole with 15 sack Name of Plugging Contractor. Address STATE OF Kansas Southwest Casing	plug back with t. 1300' with 8 s gel and 100 (If addition Southwest Ca Box 364, Gre	sand to 35 0 bbls. rot sacks ceemn aldescription is necessing Pullin at Bend, Ka	sary mud. t with 2% Bary, use BACK of Co., Inc. nsas Barton employee of over	d and ran Pulled 3 gel. Single CON:	5 sacks 7 joints. 7 joints. Wichits, Keesservation Wichits, Keesservation	cement th Squeeze COMMISSION 1967 DIVISION Mean:	d
Made bottom hole dump bailer. Circulated hole a hole with 15 sack Name of Plugging Contractor. Address STATE OF Kansas Southwest Casing well, being first duly sworn on oath	plug back with t. 1300' with 8 s gel and 100 (Haddition Southwest Ca Box 364, Gre CO Pulling Co., I, says: That I have k	sand to 35 O bbls, rot sacks ceemn aldescription is necessing Pullin at Bend, Ka UNTY OF	ary mud. t with 2% Bury, use BACK of Co., Inc. nsas Barton employee of over facts, statemen	d and ran Pulled 3 gel. Single CON:	5 sacks 7 joints. 7 joints. Wichits, Keesservation Wichits, Keesservation	cement th Squeeze COMMISSION 1967 DIVISION Mean:	rud
Made bottom hole dump bailer. Circulated hole a hole with 15 sack Name of Plugging Contractor. Address STATE OF Kansas Southwest Casing well, being first duly sworn on oath	plug back with t. 1300' with 8 s gel and 100 (Haddition Southwest Ca Box 364, Gre CO Pulling Co., I, says: That I have k	al description is necessing Pullin at Bend, Ka	ary mud. t with 2% Bury, use BACK of Co., Inc. nsas Barton employee of over facts, statemen	d and ran Pulled 3 gel. Single CON:	5 sacks 7 joints. 7 joints. Wichits, Keesservation Wichits, Keesservation	cement th Squeeze COMMISSION 1967 DIVISION Mana	rud
Made bottom hole dump bailer. Circulated hole a hole with 15 sack Name of Plugging Contractor. Address STATE OF Kansas Southwest Casing well, being first duly sworn on oath	plug back with t. 1300' with 8 s gel and 100 (Haddition Southwest Ca Box 364, Gre CO Pulling Co., I, says: That I have k	sand to 35 O bbls, rot sacks ceemn aldescription is necessing Pullin at Bend, Ka UNTY OF	ary mud. t with 2% Bury, use BACK of Co., Inc. nsas Barton employee of over facts, statemen	d and ran Pulled 3 gel. Single CON:	5 sacks 7 joints. 7 joints. Wichits, Keesservation Wichits, Keesservation	cement th Squeeze COMMISSION 1967 DIVISION Mana	rud
Made bottom hole dump bailer. Circulated hole a hole with 15 sack Name of Plugging Contractor. Address STATE OF Kansas Southwest Casing well, being first duly sworn on oath	plug back with t. 1300' with 8 s gel and 100 (Haddition Southwest Ca Box 364, Gre CO Pulling Co., I, says: That I have k	al description is necessing Pullin at Bend, Ka	ary mud. t with 2% Bury, use BACK of Co., Inc. nsas Barton employee of over facts, statemen	d and ran Pulled 3 gel. Shift (Shift (con) or (own ts, and matter Great B	5 sacks 7 joints. 7 joints. Wichits, Ka	cement the Squeeze	rud
Made bottom hole dump bailer. Circulated hole a hole with 15 sack Name of Plugging Contractor. Address STATE OF Kansas Southwest Casing well, being first duly sworn on oath above-described well as filed and the	plug back with t. 1300' with 8 s gel and 100 (If addition Southwest Ca Box 364, Gre CO Pulling Co., I , says: That I have keet the same are true s	al description is necessing Pulling at Bend, Ka	sary mud. t with 2% sary was BACK of Co., Inc. msas Barton employee of over facts, statement field me God. Box 364	d and ran Pulled 3 gel. Shift (Shift (con) or (own ts, and matter Great B	5 sacks 7 joints. 7 joints. Wichits, Ka	cement the Squeeze	d
Made bottom hole dump bailer. Circulated hole a hole with 15 sack	plug back with t. 1300' with 8 s gel and 100 (If addition Southwest Ca Box 364, Gre CO Pulling Co., I , says: That I have keet the same are true s	al description is necessing Pullin at Bend, Ka	sary mud. t with 2% sary was BACK of Co., Inc. msas Barton employee of over facts, statement field me God. Box 364	d and ran Pulled 3 gel. Shift (Shift (con) or (own ts, and matter Great B	5 sacks 7 joints. 7 joints. Wichits, Ka	cement the Squeeze	d

NUCKOLLS NO. 4

Center of the S/2 of the S/2 of the NE/4 Section 30-31S-11W Barber County, Kansas

Rigging up Rotary Tools 6/2/52 Tearing down Rotary Tools 6/20/52 Ran 5 Jts. 8-5/8" used 8 round thread casing. Set at 155' and cemented with 135 sacks.

Ran 131 Jts. 5-1/2" 8 round thread casing, Set at 4,323.50' and cemented with 200 sacks of sack cement.

FORMATION	FROM	<u>10</u>
Surface Soil	0) feet 40 feet
Clay and surface rock	- 40	120
Red Gravel and Sand and Redbed	120	155
Redbed and Sand	155	
Shale and Shells	560	1300
Shale and Lime	1300	
Shale	1875	5 .
Shale and Lime	1920	
Shale and Lime Streaks	2080	
Shale and Lime	2210	
Line	2629	
Shale and Lime	2775	
Sand	2970	
Lime	2985	19171 - 1717/
Shale and Lime	3165	5,200 5 3 /
Lime	3280	3360 5-3-67
Lime and Shale	3360	3390 HARENVATION DWISION
Sand and Lime	3390	
Lime (hard) and Sand	3585	3601
Sand	3601	
Sand and Shale	3610	
Sand, Shale, and Lime	3695	
Lime and Sand	3718	
Lime	3780	
Idme, Shale, and Sand Streaks	3810	
Lime (hard)	3838	
Lime and Shale	3945	
Lime	4000	
Lime and Shale Streaks	4040	
Lime	4074	
Lime and Shale	4119	
Line	4300	
Shale, Lime, and Chat	4315	5 4340 TOTAL DEPTH
Baker Plug at 3800'		

I, Martha Bobbitt, hereby certify that the above log is true and correct to the best of my belief and knowledge.

Martha Bobbit

Subscribed and sworn to before me this 24th day of June, 1952.

Notary Public

My commission expires: September 24, 1955.