WELL PLUGGING RECORD K.A.R.-82-3-117

•				
	•			
STATE OF KANSAS STATE CORPORATION COMMISSION	WELL PLUGGING RE K.A.R82-3-1	CORD 17 API	NUMBER 15-007-21,031	
200 Calorado Derby Bullding Wichita, Kansas 67202		LEAS	SE NAME Vogel	
	TYPE OR PRINT NOTICE: Fill out completely and return to Cons. Div.		WELL NUMBER C-1	
			Ft. from \$ Section Line	
	office within 30	days -		
Edmiston Oil	Co. Inc.		Ft. from E Section Line SW SW SE . 34 TWP. 34 RGE. 12W (E)or(W	
LEASE OPERATOR Edmiston Oil 1260 Ks. St.	Dank Blug.			
ADDRESS Wichita, Kan	sas 67202	CON	NTY <u>Barber</u>	
PHONE#(316) 265-5241 OPERA	TORS LICENSE NO. 504	2 Dat	e Well Completed	
Character of Well <u>Oil</u>	•	Plu	gging Commenced 3-8-88	
(OII, Gas, D&A, SWD, Input, Wa	ter Supply Well)	Plu	gging Completed 3-15-88	
Did you notify the KCC Distric	t Office prior to plu	gging this we	117 Yes	
Which KCC Office dld you notif				
is ACO-1 filed?If	not, is well log att	ached?	,	
Producing Formation)	Bottom T.D. 4870	
Producing formation	Depth to Top	•	BottomT.D4870'	
Show depth and thickness of al	Depth to Top	formations.	·	
	Depth to Top	•	·	
Show depth and thickness of al	Depth to Top	formations.	RECORD	
Show depth and thickness of al	Depth to Top	CASING Put I	RECORD Pulled out none	
Show depth and thickness of al	Depth to Top	CASING Put I	RECORD Pulled out none	
Show depth and thickness of all OIL, GAS OR WATER RECORDS Formation Content	Depth to Top	CASING Put I 331' 4-1/2" 4864	n Pulled out none ' 3431'	
Show depth and thickness of all OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner	Depth to Top I water, oil and gas From To S In which the well was	CASING Tze Puf [10-3/4" 331' 4-1/2" 4864	n Pulled out none ' 3431' Icating where the mud fluid	
Show depth and thickness of all OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the charac	Depth to Top I water, oil and gas From To S In which the well was ods used in introduciter of same and dep	CASING CASING Tive Put I 10-3/4" 4-1/2" 4864 Plugged, Ind Ing It Into th th placed, f	RECORD Pulled out none ' 3431' Icating where the mud fluid e hole. If cement or other p	
OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the charac Plugged off bottom wi	Pepth to Top I water, oil and gas From To s In which the well was ods used in introduct ter of same and dep th sand to 4450' and	CASING Tize Puf I 10-3/4" 331' 4-1/2" 4864 plugged, Ind ing It Into the placed, for the placed of	n Pulled out none 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612'.	
OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the charac Plugged off bottom wi	Depth to Top I water, oil and gas From To s In which the well was ods used in introduct ter of same and dep th sand to 4450' and of 83 joints of 4-1/	CASING Tize Puf I 10-3/4" 331' 4-1/2" 4864 plugged, Ind ing It Into the placed, for the placed, for the placed in the placed	n Pulled out none 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612', Jugged surface with 3 hulls	
Show depth and thickness of all OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the character of the plugged off bottom with the plugged off bottom with the plugging complete.	Pepth to Top I water, oil and gas From To S In which the well was ods used in introduct ter of same and dep th sand to 4450' and of 83 joints of 4-1, gel, 1 hull, plug ar	CASING Tize Puf I 10-3/4" 4-1/2" 4864 plugged, Ind ing It Into th th placed, f 4 sacks cemen 2" casing. P ind 150 cement,	n Pulled out none ' 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612', 1ugged surface with 3 hulls 60740 pos, 6% gel.	
Show depth and thickness of all OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the character of the plugged off bottom with the plugged off bottom with the plugging complete. (If additional description of the plugging complete of the plugging	Prom To Some of the sand to 4450 and of 83 joints of 4-1, gel, 1 hull, plug ar	CASING Tize Puf I 10-3/4" 331' 4-1/2" 4864 plugged, Ind ing It Into th th placed, f 4 sacks cemen 2" casing. P ind 150 cement, use BACK of	n Pulled out none ' 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612', 1ugged surface with 3 hulls 60740 pos, 6% gel.	
Show depth and thickness of all OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the character of the plugged off bottom with the plugged off bottom with the plugging complete.	Prom To Some of the sand to 4450 and of 83 joints of 4-1, gel, 1 hull, plug ar	CASING Tize Puf I 10-3/4" 331' 4-1/2" 4864 plugged, Ind ing It Into th th placed, f 4 sacks cemen 2" casing. P ind 150 cement, use BACK of	n Pulled out none ' 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612', 1ugged surface with 3 hulls 60740 pos, 6% gel.	
Show depth and thickness of all OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the character of the plugged off bottom with the plugged off bottom with the plugging complete. (If additional description of the plugging complete of the plugging	Prom To Some of the sand to 4450 and of 83 joints of 4-1, gel, 1 hull, plug ar	CASING CASING Tize Put I 10-3/4"	n Pulled out none ' 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612', 1ugged surface with 3 hulls 60740 pos, 6% gel.	
Show depth and thickness of all OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the charactor of Plugging Complete. (If additional described in the plugging Contractor of Plu	I water, oil and gas From To S In which the well was ods used in introduct ter of same and dep th sand to 4450' and of 83 joints of 4-1/gel, 1 hull, plug ar ription is necessary, Kelso Casing Pullir	CASING Tize Puf I 10-3/4" 331' 4-1/2" 4864 Plugged, Inding It Into the placed, for the placed, for the placed, for the placed for the plac	n Pulled out none ' 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612', 1ugged surface with 3 hulls 60740 pos, 6% gel.	
Show depth and thickness of all OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the charactor plugged off bottom with a state of the charactor of the plugging Complete. (If additional described in the charactor of the character of the	I water, oil and gas From To S In which the well was ods used in introduct ter of same and dep th sand to 4450' and of 83 joints of 4-1 gel, 1 hull, plug ar Tiption is necessary, Kelso Casing Pullir Chase, Kansas 67524	CASING Tize Put I 10-3/4" 331' 4-1/2" 4864 I plugged, Ind Ing It Into the the placed, for the placed, for the placed, for the placed, for the placed in the place	n Pulled out none 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612'. lugged surface with 3 hulls 60/40 pos, 6% gel. this form.) License No. 6050	
OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the charactor plugged off bottom with a state of the plugging Complete. If additional described well, being the state of the s	I water, oil and gas From To S In which the well was ods used in introduct ter of same and dep th sand to 4450' and of 83 joints of 4-1/gel, 1 hull, plug ar ription is necessary, Kelso Casing Pullir Chase, Kansas 67524 COUNTY OF Rice	CASING Tize Puf I 10-3/4" 331' 4-1/2" 4864 plugged, Ind ing it into th th placed, f 4 sacks cemen 2" casing. P id 150 cement, use BACK of ing, Inc.	n Pulled out none 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612', 1ugged surface with 3 hulls 60/40 pos, 6% gel. this form.) License No. 6050 ,ss. of Operator) or (Operator t I have knowledge of the fa	
OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the charactor plugged off bottom with a state of the content	Depth to Top I water, oil and gas From To S In which the well was ods used in introduct ter of same and dep th sand to 4450' and of 83 joints of 4-1/ gel, 1 hull, plug ar ription is necessary, Kelso Casing Pullir Chase, Kansas 67524 COUNTY OF Rice	CASING Tize Puf I 10-3/4" 331' 4-1/2" 4864 plugged, Ind ing it into th th placed, f 4 sacks cemen 2" casing. P id 150 cement, use BACK of ing, Inc.	n Pulled out none 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612', 1ugged surface with 3 hulls 60/40 pos, 6% gel. this form.) License No. 6050 ,ss. of Operator) or (Operator t I have knowledge of the fa	
OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method were used, state the charactor plugged off bottom with a state of the charactor of the content of the conten	I water, oil and gas From To S In which the well was ods used in introduct ter of same and dep th sand to 4450' and of 83 joints of 4-1/gel. I hull, plug ar ription is necessary, Kelso Casing Pullir Chase, Kansas 67524 COUNTY OF Rice Test duly sworn on oa contained and the ice so help me God.	CASING Tize Puf I 10-3/4" 331' 4-1/2" 4864 plugged, Ind ing it into th th placed, f 4 sacks cemen 2" casing. P id 150 cement, use BACK of ing, Inc.	n Pulled out none 3431' Icating where the mud fluid e hole. If cement or other prom feet to feet each st. Shot pipe @3811', 3612', 1ugged surface with 3 hulls 60/40 pos, 6% gel. this form.) License No. 6050 ,ss. of Operator) or (Operator t I have knowledge of the fa	


00 Calorado Der Ichita, Kansas	67202		LEASE NAME VOS		
		TYPE OR PRINT	WELL NUMBER C-1		
ane		nd return to Cons. Div.	Ft. from \$ Section Line		
			Ft. fr	om E Section Line . SE	
EASE OPERATOR_	Edmiston Oil Co.	, Inc.	SEC. 34 TWP. 34	RGE. 12W (E)or(W)	
1260 Ks. St. Bank Bldg. Wichita, Kansas 67202			COUNTY Barber		
IONE#(316, 265	-5241 OPERATORS	LICENSE NO. 5042	Date Well Compl	eted	
naracter of Wel	0i1	•	Plugging Commen	ced <u>3-8-88</u>	
Oli, Gas, D&A,	SWD, Input, Water	Supply Well)	Plugging Comple	ted 3-15-88	
ld you notify 1	the KCC District Of	fice prior to plugging t	his well? Yes		
•		Dist. #1 Dodge		···	
ACOmt filed?	 If not	, is well log attached?			
oducing Format	ion	Depth to Top	Bottom		
now depth and 1	hickness of all wa	ter, oil and gas formati		T.D. 4870	
now depth and 1	Thickness of all wa	ter, oil and gas formati	CASING RECORD		
now depth and 1	Thickness of all wa	fer, oil and gas formati	CASING RECORD		
how depth and 1 DIL, GAS OR WAT	Thickness of all wa	From To Size	CASING RECORD	out	
now depth and 1 DIL, GAS OR WAT Formation escribe in deta laced and the	Content The manner in wathod or methods	From To Size	Put in Pulled 331 none 4864 3431	e the mud fluid wa	
how depth and 1 OIL, GAS OR WAT Formation escribe in deta laced and the ere used, sta Plugged	Content Content The manner in we method or methods te the character off bottom with s	From To Size 10-3/4' 4-1/2' Thich the well was plugge used in introducing it is of same and depth place and to 4450' and 4 sacks	Put in Pulled 331' none 4864' 3431' dd, indicating where into the hole. If come feet to come the come of the com	e the mud fluid wa ement or other plug o feet each set e @3811', 3612',	
formation escribe in detailated and the ere used, sta Plugged 3431! 10 gel.	Content Content The manner in water off bottom with spulled a total of 50 cement, 10 gel	From To Size $\frac{10-3/4}{4-1/2}$ Thich the well was plugger used in introducing it is of same and depth place	Put in Pulled 331' none 4864' 3431' d, indicating where the the hole. If come the test to be compared to the pigning. Plugged surface to the pure to	e the mud fluid was ement or other plug o feet each set e @3811', 3612', ice with 3 hulls.	
escribe in detailated and the ere used, sta Plugged 3431', Pluggin	Content Content The manner in wathod or methods to the character off bottom with spulled a rotal of 50 cement, 10 gel g Complete.	From To Size 10-3/4' 4-1/2' which the well was plugge used in introducing it is of same and depth place and to 4450' and 4 sacks and joints of 4-1/2" cast	Put in Pulled 331 none 4864 3431 dd, indicating where the hole if come feet the seement. Shot pigged surfacement, 60740 pos,	e the mud fluid wa ement or other plug o feet each set e @3811', 3612', ice with 3 hulls.	
escribe in detailated and the ere used, sta Plugged 3431', 10 gel, Pluggin (if	Content Content The manner in wathod or methods to the character off bottom with spulled a rotal of 50 cement, 10 gel g Complete, additional descript	From To Size 10-3/4' 4-1/2' which the well was plugge used in introducing it is of same and depth place and to 4450' and 4 sacks 83 joints of 4-1/2" cast 1 hull, plug and 150 c	Put in Pulled 331 none 4864 3431 dd, indicating where the hole if coment. Shot pigurent, 60740 pos, CK of this form.)	e the mud fluid was ement or other plug o feet each set be @3811', 3612', ice with 3 hulls, 6% gel.	
escribe in detailated and the ere used, sta Plugged 3431. 10 gel, Plugging ame of Plugging	Content Content Content The manner in water of bottom with spulled a rotal of 50 cement, 10 gel g Complete, additional descript	From To Size 10-3/4' 4-1/2' which the well was plugge used in introducing it is of same and depth place and to 4450' and 4 sacks 83 joints of 4-1/2" cast 1 hull, plug and 150 certains in the same and to 450' and 4 sacks 83 joints of 4-1/2" cast 1 hull, plug and 150 certains of 4-1/2" cast 1 hull, plug and 1 hull,	Put in Pulled 331 none 4864 3431 dd, indicating where the hole if coment. Shot pigurent, 60740 pos, CK of this form.)	e the mud fluid wa ement or other plug o feet each set be @3811', 3612', use with 3 hulls, 6% gel.	
escribe in detailated and the ere used, sta Plugged 3431' 10 gel, Pluggin (if the end of Pluggin and the end of Pluggin (if the end of Pluggin end end end end end end end end end en	Content Content Content The manner in we method or methods to the character off bottom with spulled a total of 50 cement, 10 gel g Complete. Contractor Ke Box 347 Ch	from To Size 10-3/4' 4-1/2' with the well was plugge used in introducing it of same and depth place and to 4450' and 4 sacks 3 joints of 4-1/2" case 1 hull, plug and 150 ce Iso Casing Pulling, Inc.	Put in Pulled 331 none 4864 3431 dd, indicating where the hole if coment. Shot pigurent, 60740 pos, CK of this form.)	e the mud fluid wa ement or other plug o feet each set be @3811', 3612', use with 3 hulls, 6% gel.	

SUBSCRIBED AND SWORN TO before me this

March 18th day of

COMMISSION 88

My Commission Expires:



CONSERVATION DIVISION FOR CP-4
Wichita, Kansas Revised 07-86

15.007-21031-00-01

CONTRACTORS WELL LOG

DEC 8 1980

UPERATOR: CONTRACTOR:

LEASE NAME: LOCATION:

COMMENCED: COMPLETED: RAM PETROLEUM CORPORATION UNION DRILLING CO., INC. VOGEL "C" #1

SW SW SE SECTION 34-34S-12W

BARBER COUNTY, KANSAS NOVEMBER 23, 1980

DECEMBER 1, 1980

0	691	REDBED & SHALE	SET 10-3/4" AT 331'	
691	4259	SHALE	WITH 275 SACKS COMMON	2% GEL.,
4259	4449	SHALE & LIME	3% CA. CL.	Ť
4449	4607	LIME & SHALE		
4607	4865	LIME	•	
4865		TD		

WE CERTIFY THAT THE ABOVE FOREGOING IS A TRUE AND CORRECT COPY OF THE LOG ON THE VOGEL "C" #1, SW SW SE SECTION 34-34S-12W, BARBER COUNTY, KANSAS.

UNION DRILLING CO., INC.

STATE OF KANSAS)ss COUNTY OF SEDGWICK)

SUBSCRIBED AND SWORN TO BEFORE ME A NOTARY PUBLIC, IN AND FOR THE AFORESAID COUNTY AND STATE AS OF THIS 5th DAY OF DECEMBER, 1980.

MY APPOINTMENT EXPIRES:

6-2-82