To: 1 041151 STATE CORFORATION COMMISSION Wichita State Office Bidg PLUGGING SECTION 130 S. Market, Room 2078 Wichita, KS 67202		AP1 NUMBER 15-151-20,763-0000	
		SE SE SE, SEC. 1	26 s, R 12 WX
		330feet 1	from S section line
Wichita, KS 67202 TECHNICIAN'S PLUGGING REPORT 2-27		330 - feet 1	from E section line
Operator License 3 30333 Lease Name Hoskinson Well 5 1			
	American Petroleum Exploration	County Pratt	135,53
Name& Address	P.O. Box 48304	Well Total Depth	4170 feet
	Wichita, KS 67201	Conductor Pipe: Size	•
		Surface Casing: Size 8	5/8 feet 320
Abandoned	Oli Weil X Gas Weil	Imput WellSWD W	ell
Other well as hereinafter indicated			
Plugging Contractor Mike's Testing & Salvage Inc. License Number 31529			
Address P.O. Box 209, Chase, KS 67524			
Company t	o plug at: Hour: 9:45 a.m. Day:	27 Honth: 2	Year: 1996
Plugging proposal received from Manny Boatwright			
(company name) Mike's Testing & Salvage Inc. (phone) 316-938-2943			
were: 4½" at 4166' w/250 sx cement, PBTD 4161', Perfs at 3626'			
1st plug sand back to 2500' and dump 4 sx cement on top of sand through bailer,			
2nd plug pump 300 lbs. hulls, 10 sx gel, 50 sx cement, 10 sx gel, 100 lbs. hulls, release			
8 5/8" wiper plug and pump 100 sx cement.			
· ·	<u> </u>		- 100
	Plugging Propo	sal Received byBi	ill Johnson) 6 芸
(TECHNICIÁN)			
Plugging Operations attended by Agent?: All X Part None			
	ns Completed: Hour: 10:15 a.mDay:		
ACTUAL PLUGGING REPORT Junk left in hole. Top of 2 3/8" @ 2585' (App.1576' of tubing left in hole some years back. Tubing was dropped down hole while servicing well and were unable to fish what remains in hole.)			
1st plug sanded back to 2500' and dumped 4 sx cement on top of sand bridge through bailer,			
2nd plug pumped down 8 5/8" surface pipe with 300 lbs. hulls, 10 sx gel, 50 sx cement, 10 sx			
gel, 100 lbs. hulls, released 8 5/8" wiper plug and pumped 125 sx cement.			
Maximum pressure 500 psi and shut in 100 psi.			
Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2200' of 42" casing.			
(if additional description is necessary, use BACK of this form.)			
I Ned id Oxxivaxizi Jobserve this plugging.			
DATE MAR 05 1996			
FORM CP-2/3 Ray, 01-84			