

TO: STATE CORPORATION COMMISSION
CONSERVATION DIVISION - PLUGGING
130 SOUTH MARKET, SUITE 2078
WICHITA, KANSAS 67202

API Well Number: 15-015-23988-01-00
Spot: SWSWSWSW Sec/Twnshp/Rge: 10-25S-3E
280 feet from S Section Line, 155 feet from W Section Line
Lease Name: GOERING Well #: 10-14-10-11H
County: BUTLER Total Vertical Depth: 6894 feet

Operator License No.: 34633
Op Name: SOURCE ENERGY MIDCON LLC
Address: 1805 SHEA CENTER DR., STE 100
HIGHLANDS RANCH, CO 80129

String	Size	Depth (ft)	Pulled (ft)	Comments
	II 7	3522		205 SX
PROD	0	6894		0 SX
SURF	9.625	300		130 SX

Well Type: OIL UIC Docket No: _____ Date/Time to Plug: 12/31/2013 12:00 AM
Plug Co. License No.: 99975 Plug Co. Name: COMPANY SERVICING TOOLS
Proposal Revd. from: ROB BURKHART Company: _____ Phone: (620) 218-0329

Proposed Plugging Method: While this well was not "officially" plugged, mother nature plugged it naturally due to a lateral collapse. This well was spud 8/31/13 and completed on 10/24/13. This well was producing from 10/25/13 until it was shut in 12/4/13 when it was scheduled for a cleanout and stimulation. In January some work was done but the pump was still not working. On 2/3/14 the pump was pulled and found to be packed with sand and drilling mud. We would like to officially close out API#15-015-23988-01-00. We applied for a new API# for a lateral redrill that began 3/17/14 and has yet to be completed. Estimated completion date is mid June 2014. Two sets of drill cuttings have been sent to the Geological Society so we are trying to keep the 2 APIs separate. Please accept this plugging application so we can close out this API. Thank you.

Plugging Proposal Received By: _____ WitnessType: PARTIAL
Date/Time Plugging Completed: 12/31/2013 12:00 AM KCC Agent: PATRICK SHIELDS

Actual Plugging Report:

WHILE THIS WELL WAS NOT "OFFICIALLY" PLUGGED, MOTHER NATURE PLUGGED IT NATURALLY DUE TO A LATERAL COLLAPSE. THIS WELL WAS SPUD 8/31/2013 AND COMPELTED ON 10/24/13. THIS WELL WAS PRODUCING FROM 10/25/13 UNTIL IT WAS SHUT IN 12/4/13 WHEN IT WAS SCHEDULED FOR A CLEANOUT AND STIMULATION. IN JANUARY SOME WORK WAS DONE BUT THE PUMP WAS STILL NOT WORKING. ON 2/3/14 THE PUMP WAS PULLED AND FOUND TO BE PACKED WITH SAND AND DRILLING MUD. WE WOULD LIKE TO OFFICIALLY CLOSE OUT API#15-015-23988-01-00.

Perfs:

MTD = 6,836
Interval Inv. = 58'

Received
KANSAS CORPORATION COMMISSION
SEP 02 2014
CONSERVATION DIVISION
WICHITA, KS

Remarks:

Plugged through:

District: 02

Signed [Signature]
9.9.14 CKM (TECHNICIAN)