1 050792

15-165-38405-00-01 Continuation of 1050580 Dated 7-16-85

πő:		API NUMBER 15-	
STATE CORF Conservati	PORATION COMMISSION TON DIVISION - PLUGGING SECTION	C SE , SEC. 13 , T 18 S, R 16 W/EX	
200 COLORA	ADO DERBY BUILDING (ANSAS 67202	1320 feet from S section line	
	N'S PLUGGING REPORT	1320 feet from E section line	
•	lcense /	Lease Name Riedel Well # 1 OWWO	
Operator: Name& Address	Kansas Corporation Commission	County	
	200 Colorado Derby Building	Well Total Depth 3458 feet	
	Wichita, KS 67202-1286	Conductor Pipe: Size feet	
•		Surface Casing: Size 20" feet 70'	
Abandoned	Oll Well Gas Well X	Input Well SWD Well D&A	
	l as hereinafter indicated		
Plugging (Contractor Halliburton Services	License Number	
Address	P. O. Box 579, Great Bend, KS		
	o alug at: Hour: 4:30 pm Day: 7	Month: April Year:19 86	
Plugging (proposal received from S	316-225-6760	
(company r	name)	(phone) 316-225-6760	
were: Ha	alliburton pressured well with 300	psi - would not take fluid. Some leakage	
arour	nd 7" casing. Repressured well to	525 psi Rate established at 3 bbls per	
		eeze annularr space between 7" and 15"	
		Re-	
	Plugging Propo	sal Recelved by Steve Durrant (TECHNICIAN)	
	그리면 조건이 휴 그로 살았다.		
	Operations attended by Agent?: Al		
Operation	s Completed: Hour: 6:30 pm Day:	7 Month: April Year:19 86	
ACTUAL PL	UGGING REPORT Pumped 200 sx Class	H cement with 2% gel 3% cc. Pump	
press	sure remained at 500 psi throughou	t squeeze. Pressure was still holding at	
375 r	osi after 10 minutes.	Annes	
		STATE CORPORATION COMMISSION	
		APR 1 5 1986	
*.		CONSCIOUS SE	
	Hood Classey and 200	Wichita, Kansas	
Remarks:	Used Class H cement 2% gel 3% cc	necessary, use BACK of this form.)	
, ,			
i (did /	did not) observe this plugging.	Signed Richard W Larin	
=		a signed force of the transfer of	

15-165-30405-00-01.

KCC/KDHE JOINT OIL/GAS REGULATORY OFFICE		
DATE April 8, 1986	[] New Situation [] Response to Request	
OPERATOR E. C. Wedell # (Decease	X&	
NAME Responsibility for plugging given to the Kansas Corporation Commission ADDRESS	LOCATION C SE ,SEC 13 ,T 18S,R 16 W LEASE Riedel Well # 1 OWWO	
PHONE NO. OPER. OTHER	COUNTY Rush	
REASON FOR INVESTIGATION: Don Ubel, District 1	Geologist, reported this well as	 5
abandoned For further field reports - se	ee file.	֡֝֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓
	Geologist, reported this well as ee file.	5
PROBLEM: Well flowing	}	
	FASE	֧֭֚֚֚֚֚֚֚֚֡֝֝֝֝֝֝֝֝֝֝֝֟֝֝ ֓֓֓֞֞֞֓֓֓֓֞֞֩֞֩֞֞֩֓֓֓֓֞֩֞֩֞֓֓֓֞֡
		·
PERSON(S) CONTACTED:		-
- Enson(o) commonder		-
ACTION ***********************************	large gate valve coins into 15 1/2" wins	-
with cement on top. Flow-mud (new looking Could not pump into well with 200 psi. Sh	12	<u>:</u> }
truck go to 500 psi. At 300, elbow at head	d started leaking - shut down.	: 5
4-7-86 Cut off elbow and chipped out cemen	t around nipple threads. Screwed on 2"	<u>.</u>
collar and well support plate for high pre-	ssure squeeze. Halliburton pressured well wi	.th
300 psi - would not take fluid. Some leak	age around weld and 7" casing. Repressured	
well to 525 psi. Rate established at 3 bb	ls per min. Decided to mix cement and squeez	е.
Pumped 200 sx class H cement with 2% gel 3	% cc. Pump pressure remained at 500 psi	-
throughout squeeze. After shut pressure,	was still holding 375 psi in 10 minutes.	-
	following contractors were involved in the photos taken:	=
ACTION/RECOMMENDATIONS Halliburton Cementing,		5
Service, Holpriek Dirt Service. Location	*	
		1
2 days. Both wells on this section have be	een cut off and capped below ground level.	
STATE CORPORAL	TION COMMISSION	-
Cond 1 Conservation District	5 1986	_
CONSERVATI	Steve Durrant ON DIVISION	_
Wichita.	Kansas	