. T (	070054	API NUMBER 15- 175-21,692 -00-00
9,5	TOUTION COUNTSSION	NE NE , SEC. 9 , T 33 S, R 32 V)
Wichita State	Office Blag PLUGGTRG SEGTION	
30 S. Market Wichita, Y	t, Room 2078 KS 67202	660 feet from NXX section iii
	I'S PLUGGING REPORT	-660 feet from E section (in
Operator L	/ F / O	Lease Name Milhon A Well & 2
	Anadarko Petroleum Corporation	County Seward 202,
	P.O. Box 351	Well Total Depth 6225 fe
	Liberal, KS 67905-0351	Conductor Pipe: Sizefeet
		Surface Casing: Size 8 5/8 feet 1620
Abandoned	Oll WellGas Well	Input Well SWD Well D&A
	l as hereinafter indicated	
Plugging	Contractor Cheyenne Drilling, In	nc. License Number 5382
	P.O. Box 916, Garden City, KS 678	
		21 Month: 1 Year:19 <u>98</u>
	proposal received from Jim Ba	arlow
	Anadarko Petroleum Corp.	(phone) 316-624-625
. 1	to fill hole with heavy mud and spo	t cement through drill pipe
lst plug	at 3000° with 100 sx cement, 2nd	plug at 1650' with 50 sx cement.
	at 800' with 40 sx cement, 4th plu	3 4 1
		FIAN 9 7 1998
5th plug	at 40-0 with 10 sx cement, 6th p.	lug to circulate fathole with 15 sx cement,
7th plug	to circulate mousehole with 10 sx	cement. With a Kansas
	Plugging Pro	posal Recolved by Scott Alberg
		(TECHNICIAN)
Plugging	g Operations attended by Agent?:	AllPartNone_X
Operatio	ons Completed: Hour: 7 a.m. Day:	21 Month: 1 Year:19 98
	PLUGGING REPORT 1st plug at 3000'	with 100 sx cement,
	at 1650° with 50 sx cement, 3rd p	
	at 460° with 40 sx cement,	rug at 800 with 40 sx cement,
4th brug		
5th plug	at 40-0° with 10 sx cement,	
	at 40-0' with 10 sx cement, ' to circulate rathole with 15 sx cer	nent,
6th plug	at 40-0 with 10 sx cement,	
6th plug 7th plug	to circulate rathole with 15 sx cer  to circulate mousehole with 10 sx of  Used 60/40 Pozmix 6% gel by Hall	iburton.  Is necessary, use BACK of this form.)
7th plug Remarks	to circulate rathole with 15 sx cer to circulate mousehole with 10 sx of to circulate rathole with 15 sx cer to circulate mousehole with 15 sx cer to circulate mousehole with 15 sx cer to circulate mousehole with 10 sx of to circulate mousehole with 15 sx cer to circulate mousehole with 10 sx of to circulate mousehole with 15 sx cer to circulate mousehole with 10 sx of to circul	iburton.  Is necessary, use BACK of this form.)
7th plug	to circulate rathole with 15 sx cer  to circulate mousehole with 10 sx of  Used 60/40 Pozmix 6% gel by Hall	iburton.  Is necessary, use BACK of this form.)