•	± 060578		API NUMBER 15- 151-21,195-00-00				
	To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202			API NUMBER 15-	151-21,1	.95 - 80-60	
				SW SW NW , SEC			
				2970			
	TECHNICIAN'S PLUGGING REPORT						
				4950 feet from E section line Lease Name_Smith 'PP' Well 1 1			
	Operator License / 5171						
	Name&	TXO Production (Corp.	County	Pratt		149.50
		200 West Douglas	s, Suite 300	Well Total Dep	th	4600	feet
		Wichita, KS 6720	02 ·	Conductor Pipe	: Size	feet	<u> </u>
			·	Surface Casing	: Size 8 5	/8feet	411
	Abandoned	Oll Weil	_ Gas Well <u> X</u>	input Well	SWD Wel	I	D&A
	Other well	l as hereinafter	indicated	 			
	Plugging Contractor Clarke Corporation License Number 5105						
	Address	Box 187, Medicin	e Lodge, KS 671	04			
	Company to	plug at: Hour:	1:00 pm Day:_	29 Month:	May	Year:19	85
	Plugging (proposal received	from	Elmo Morgenstern			
	(company (name) Clarke		_	(1	phone) 316	-886-5665
	were: 4 1/2" at 4599' PBTD 4160' Perfs at 4126-32 & 4164-68'						
	1st plug sand back to 4075' and dump 4 sx cement on top of sand through bailer						
	2nd plug squeeze well with 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls,						
	release 8 5/8" rubber plug and pump 150 sx cement.						
	•						•
	Plugging Proposal Received by Paul A. Luthi						
		<u> </u>			(7	TECHNICIAN))
	Plugging (Operations attend	ed by Agent?: /	NII <u>X</u> Part	, 	None	
	Operations	s Completed: Hou	r: 2:30 pm Day:	29 Month:	May	Year:19	9 85
	ACTUAL PL	ugging REPORT 1st	plug sanded ba	ck to 4075' and dur	nped 4 sx		
	sand through bailer, 2nd plug squeezed well with 3 sx hulls, 15 sx gel, 50 sx cement, 10						
	sx gel. 1	sack hulls, rele	ased 8 5/8" rub	ber plug and pumped	+thicute	ement	
				ŞIĄJE	10 MOITAFITHAUD 2 - 16 - 20	ONIMINA	
					MAY 3 1 19	0.00	
					NSERVATION DIV	licion	
	Maximum p	ressure 400 psi a	nd shut in 250	psi.	Wichita, Kansa		
	Remarks: Recovered 2400' 4 1/2" casing. Used 60/40 Pozmix 2% gel 3% cc by BJ-Titan [If additional description is necessary, use BACK of this form.)						
1 N	VOIO	' – 1)		necessary, use <u>ba</u>	<u>.CK</u> OF THIS	; form.)	C
	' \ (64 d+ /9; \	数数数数数数 observe	this plugging.		11	A H	- 40
DATE	<u> </u>	- 0.0	•	\$Igned ac	(TECHNIC	HAND	<u> </u>
INV. N	o. <u>835</u>	5-29)RM CP-2/3 Rev.01-84
				_			