

15-025-00027-00-00

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Tennessee Gas
Lease Owner Transmission Company Address P. O. Box 513, Chase, Kansas
(Applicant)

Lease (Farm Name) C. J. Knop Well No. 1

Well Location 660' fr WL & 660' fr NL of SW/4 Sec. 1 Twp. 34S Rge. (E) (W) 21

County Clark Field Name (if any) Wildcat

Total Depth 565 Oil Gas Dry Hole Dry Hole

Was well log filed with application? No If not, explain: _____

Not available. Will file as soon as possible.

Date and hour plugging is desired to begin July 6, 1956

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

P. H. Lenhart Address P. O. Box 513, Chase, Kansas

Plugging Contractor Sterling Drilling Company

Plugging Contractor's License No. _____

Address Sterling, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Tennessee Gas Transmission Company Address P. O. Box 513, Chase, Kansas

and payment will be guaranteed by applicant.

Glen E. Amoser
Applicant or Acting Agent

Date July 16, 1956

PLUGGING
FILE SEC. 1 T. 34 R. 21W
BOOK PAGE 77 LINE 40

RECEIVED
STATE CORPORATION COMMISSION
JUL 18 1956
CONSERVATION DIVISION
WICHITA, KANSAS



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

July 9, 1956

Well No. 1
Lease Knop
Description CNW SW 1-34-21W
County Clark
File No. 77-40

Tennessee Gas Transmission Co.
Box 513
Chase, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rivos, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

By S. S. Greider
S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor