

KANSAS
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:
Jewel M. Ogden, Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

File No. _____ County: CLARK

Location: NW-NW-NE Sec. 5 Twp. 34 Rge. 23 (E) (W)

Name of Field: _____ Total Depth: 7243'

I have this date completed supervision of plugging of:

Lease Name: T. J. KLINGER Well No. 1

Operator's Full Name: SUNCLAR OIL & GAS CO

Complete Address: Box 466 CHASE, KANS

Plugging Contractor: CO TOOLS

Address: _____ License No. _____

Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ D & A

Other well as hereafter indicated: _____

Was any delay in plugging operations caused by Conservation Division Agent? Yes _____ No

If yes how long? _____ Reason: _____

Operation Completed: Hour 2:00 PM Day 14 Month JUNE Year 1960

The above well was plugged as follows:

20"-50' - 13 3/8"-714' PVC - 9 7/8" - 2790' w/200
RECOVERED 2000' - 9 7/8" - FILLED HOLE w/MUD
TO 700' - SET PLUG & HULLS w/30 SV ENT -
FILLED w/MUD TO 35' - PLUG & HULLS w/15 SV
ENT CAP.

JUL 6 1960

CONSERVATION DIVISION

Signed: Frank Brock
Conservation Division Agent

Reviewed: J. Lewis Brock
Field Supervisor

Remarks: 7/7/60
1615-W

KANSAS.
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:
Jewel M. Ogden, Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

File No. _____ County: Clark
Location: C NW NW NE Sec. 5 Twp. 34 Rge. 23 (E) (W)
Name of Field: _____ Total Depth: 5450

I have this date completed supervision of plugging of:

Lease Name: Klinger Well No. 1
Operator's Full Name: Sundair Oil & Gas Co.
Complete Address: Box 521, Tulsa Okla.
Plugging Contractor: Knight Casing Pulling Co.
Address: East Bend Road License No. _____
Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ D & A

Other well as hereafter indicated: _____
Was any delay in plugging operations caused by Conservation Division Agent? Yes _____ No
If yes how long? _____ Reason: _____

Operation Completed: Hour 7pm Day 23 Month June Year 1960

The above well was plugged as follows:

Hole was filled with heavy mud to 2800' 10' of sand
& 7500' cement dumped from 2800' Pulled pipe.
Hole mudded to 300' 10' rock body to 250' 3000' of
cement poured on body - Hole mudded to 250' 10' rock
body to 10' Cement poured to base of cellar.

Signed: [Signature]
Conservation Division Agent

Reviewed: [Signature]
Field Supervisor

Remarks:

RECEIVED
STATE CORPORATION COMMISSION

JUL 7 1960

CONSERVATION DIVISION