	1 040301	API NUMBER 15-151-21, 181 -00-00
CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING		W/2 NW SW , SEC. 2 , T 28 S, R 12 W
	KANSAS 67202	feet from \$ section ill
TECHNICIAN'S PLUGGING REPORT		feet from E section lin
Operator	License # 5316	Lease Name Hissons Well #
	Falcon Exploration Inc.	County Pratt 147.8
Name& Address	125 North Market, Suite 1075	Well Total Depth4550 fee
	Wichita, KS 67202	Conductor Pipe: Sizefeet
		Surface Casing: Size 10 3/4 feet 279
Abandoned	Oll Well X Gas Well	Input WellD&A
	1 as hereinafter indicated	
		Pullers License Number 4635
•	P.O. Box 768, Great Bend, KS 675	
		18
Plugging	proposal received from Gary Burk	<u>e</u>
(company)	name) Great Bend Casing Pullers	
1 mbanl.	"" Great Bend Casing Pullers	(phone)316-792-6970
	g" at 4168' PBTD 4151' Perfs at	
were: 41	½" at 4168' PBTD 4151' Perfs at	
lst plug s	g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx	3965-68, 4001-04, 4058-60' cement on top of sand through bailer,
were: 41 1st plug s 2nd plug p	sand back to 3915' and dump 4 sx	3965-68, 4001-04, 4058-60' cement on top of sand through bailer,
were: 41 1st plug s 2nd plug p	g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx	3965-68, 4001-04, 4058-60' cement on top of sand through bailer,
were: 41 1st plug s 2nd plug p	sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement.	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4"
were: 41 1st plug s 2nd plug p	sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement.	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson
were: 4 ¹ 1st plug s 2nd plug p wiper plug	sand back to 3915' and dump 4 sx bump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Prop	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN)
were: 4½ 1st plug s 2nd plug p wiper plug	g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx bump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Prop	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN)
were: 4½ 1st plug s 2nd plug p wiper plug Plugging 0 Operations	g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Propoperations attended by Agent?: As Completed: Hour: 12:30 p.flay:	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN) II Part None
were: 41 1st plug s 2nd plug p wiper plug Plugging C Operations	g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Prop Operations attended by Agent?: A s Completed: Hour: 12:30 p. Ray:	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN)
lst plug s 2nd plug p wiper plug Plugging (Operations ACTUAL PLU sand brids	g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Propugations attended by Agent?: A completed: Hour: 12:30 p. fay: UGGING REPORT 1st plug sanded back ge with bailer,	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN) II x Part None 18 Month: 7 Year:19 89 ck to 3915' and dumped 4 sx cement on top of
were: 41 1st plug s 2nd plug p wiper plug Plugging C Operations ACTUAL PLU sand bridg 2nd plug p	g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Propugations attended by Agent?: A completed: Hour: 12:30 p.#ay: UGGING REPORT 1st plug sanded back with bailer, pumped down 10 3/4" surface pipe	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN) II x Part None 18 Month: 7 Year:19 89 ck to 3915' and dumped 4 sx cement on top of with 400 lbs. hulls, 10 sx gel, 50 sx cement, 1
lst plug s 2nd plug p wiper plug Plugging (Operations ACTUAL PLU sand brids 2nd plug p sx gel, 1(g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Proportions attended by Agent?: A completed: Hour: 12:30 p. Ray: UGGING REPORT 1st plug sanded base with bailer, pumped down 10 3/4" surface pipe 20 1bs. hulls, released 10 3/4" w	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN) II x Part None 18 Month: 7 Year:19 89 ck to 3915' and dumped 4 sx cement on top of with 400 lbs. hulls, 10 sx gel, 50 sx cement, 1 iper plug and pumped 130 sx Cement.
lst plug s 2nd plug p wiper plug Plugging (Operations ACTUAL PLU sand brids 2nd plug p sx gel, 1(g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Propugations attended by Agent?: A completed: Hour: 12:30 p.#ay: UGGING REPORT 1st plug sanded back with bailer, pumped down 10 3/4" surface pipe	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN) II x Part None 18 Month: 7 Year:19 89 ck to 3915' and dumped 4 sx cement on top of with 400 lbs. hulls, 10 sx gel, 50 sx cement, 1 iper plug and pumped 130 sx Cement.
lst plug s 2nd plug p wiper plug Plugging (Operations ACTUAL PLU sand brids 2nd plug p sx gel, 1(g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Proportions attended by Agent?: A completed: Hour: 12:30 p. Ray: UGGING REPORT 1st plug sanded base with bailer, pumped down 10 3/4" surface pipe 20 1bs. hulls, released 10 3/4" w	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN) II x Part None 18 Month: 7 Year:19 89 ck to 3915' and dumped 4 sx cement on top of with 400 lbs. hulls, 10 sx gel, 50 sx cement, 1 iper plug and pumped 130 sx Cement.
lst plug s 2nd plug p wiper plug Plugging (Operations ACTUAL PLU sand brids 2nd plug p sx gel, 1(Maximum pr	g" at 4168' PBTD 4151' Perfs at sand back to 3915' and dump 4 sx pump 4 sx hulls, 10 sx gel, 50 sx g and pump 130 sx cement. Plugging Propoperations attended by Agent?: As Completed: Hour: 12:30 p. Ray: UGGING REPORT 1st plug sanded back with bailer, pumped down 10 3/4" surface pipe 20 1bs. hulls, released 10 3/4" we ressure 350 psi and shut in 150 pulsed 60/40 Pozmix 6% gel by B.J.	3965-68, 4001-04, 4058-60' cement on top of sand through bailer, cement, 10 sx gel, 1 sx hulls, release 10 3/4" osal Received by Mike Wilson (TECHNICIAN) II x Part None

MV. NO. 25473)

FORM CP-2/3 Rev.01-84