# STATE OF KANSAS STATE CORPORATION COMMISSION KANSAS (ORPORATION COMMISSION COMPORATION COMMISSION) 130 S. Market, Room 2078 Wichita, KS 67202

FORM CP-1 Rev. 03/92

FEB 2 5 2002

(signature)

WELL PLUGGING APPLICATION FORM (PLEASE TYPE FORM and File ONE Copy) API # 15-129-00228-0000 (Identifier number of this well) (Identifi , WELL OPERATOR BP AMERICA PRODUCTION COMPANY \_ KCC LICENSE # ADDRESS P. O. BOX 3092, WL1, RM 3.329 (operator's) \_CITY\_ STATE \_\_\_\_ LEASE KINSLER 'B' \_\_\_\_\_\_\_WELL # 1 \_\_\_\_\_SEC. 08 \_\_T. 32S R. 40W (East West) - SW - NW - SE SPOT LOCATION/QQQQ COUNTY MORION \_1790 S FEET (in exact footage) FROM SN (circle one) LINE OF SECTION (NOT Lease Line) <u>2440 E</u> FEET (in exact footage) FROM W (circle one) LINE OF SECTION (NOT Lease Line) Check One: OIL WELL\_\_\_ GAS WELL\_X D&A\_\_\_SWD/ENHR WELL\_\_\_ DOCKET #\_\_\_\_\_ CONDUCTOR CASING SIZE NONE SET AT CEMENTED WITH SURFACE CASING SIZE 10 3/4" SET AT 372' CEMENTED WITH -250 PRODUCTION CASING SIZE 7" SET AT \_\_\_\_2183' CEMENTED WITH \_\_\_ 125 LIST (ALL) PERFORATIONS and BRIDGEPLUG SETS: SLOTTED 5.5" LINER SET @ 2170-2316' \_\_ T.D. <u>2316'</u> PBTD\_\_\_\_\_ ANHYDRITE DEPTH \_ ELEVATION 3315'-G.L. (G.L./K.B.) (Stone Corral Formation) CONDITION OF WELL: GOOD X POOR CASING LEAK. JUNK IN HOLE ---PROPOSED METHOD OF PLUGGING SEE ATTACHED PROCEDURES (If additional space is needed attach separate page) IS WELL LOG ATTACHED TO THIS APPLICATION AS REQUIRED? NO IS ACO-1 FILED? YES If not explain why? MISSING LOG - CAN NOT LOCATE ANY LOG ON THIS WELL (SEE ATTACHED) PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-101 et. seq. AND THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION. LIST NAME OF COMPANY REPRESENTATIVE AUTHORIZED TO BE IN CHARGE OF PLUGGING OPERATIONS. SUE SELLERS \_\_\_\_\_\_PHONE # (281)\_366-2052 ADDRESS P. O. BOX 3092, WL 1, RM 3.329 City/State HOUSTON, TEXAS 77253-3092 PLUGGING CONTRATOR HALLIBURTON SERVICES \_\_\_\_ KCC LICENSE # 528797 (contractor's) (company name) \_\_ PHONE # ( ) \_\_ ADDRESS-PROPOSED DATE AND HOUR OF PLUGGING (If Known?)\_\_\_ PAYMENT OF THE PLUGGING FEE (K.A.R. 82-3-118) WILL BE GUARANTEED BY OPERATOR OR AGENT

DATE: 02/22/02 AUTHORIZED OPERATOR/AGENT:



## Kansas Corporation Commission

Bill Graves, Governor John Wine, Chair Cynthia L. Claus, Commissioner Brian J. Moline, Commissioner

#### NOTICE OF RECEIPT OF WELL PLUGGING APPLICATION (CP-1)

BP America Production Company 2225 West Oklahoma Avenue Ulysses, KS 67880

March 07, 2002

Re: KINZLER B #1

API 15-129-00228-00-00

SWNWSE 8-32S-40W, 1790 FSL 2440 FEL

MORTON COUNTY, KANSAS

#### Dear Operator:

This letter is to notify you that the Conservation Division is in receipt of your plugging proposal, form CP-1, for the above-captioned well.

Your CP-1 has been reviewed by the Conservation Division central office for completeness and to verify license numbers. The plugging proposal will now be forwarded to the district office listed below for review of your proposed method of plugging.

Please contact the district office for approval of your proposed plugging method at least five (5) days before plugging the well, pursuant to K.A.R. 82-3-113 (b). If a workover pit will be used during the plugging of the well it must be permitted. A CDP-1 form must be filed and approved prior to the use of the pit.

The Conservation Division's review of form CP-1, either in the central or district office, does not include an inquiry into well ownership or the filing operator's legal right to plug the well.

This notice in no way constitutes authorization to plug the above-captioned well by persons not having legal rights of ownership or interest in the well. This notice is void after ninety (90) days from the above date.

District: #1

210 E Frontview, Suite A Dodge City, KS 67801

(316) 225-8888

David P. Williams **Production Supervisor** 

Plugging Application Kinsler B 1 – Abandonment Section 08, T32S, R40W Morton County

The application attached is to abandon the Kinsler B 1. BP America Production Company is abandoning this well since there is a fish stuck in the hole. It is doubtful that the fish can be recovered and commercial gas production obtained from this wellbore.

VINSAS CORPORATION COMMISSION

FEB 2 5 2002

CONSERVATION DIVISION

### Plugging Procedure for the Kinsler B 1 Section 08 T32S R40W Morton County, Kansas

NOTE – NOTIFY KCC DISTRICT OFFICE AT LEAST FIVE DAYS IN ADVANCE OF WORK.

This procedure was approved via a telephone conversation between Cary Spohn (BP representative) and Steve Durant (KCC) on February 6, 2002.

There is a Halliburton packer stuck at 2101', with a top of 3.5" tubing fish at 1757'.

- 1. Arrive on location, perform RAT/JSA. RUSU.
- 2. Set 7" CIBP at 1700'.
- 3. Dump 7 sacks of cement on CIBP using dump bailer.
- 4. Pressure test casing to 300 psi.
- 5. Perforate squeeze holes at 690'.
- 6. Establish circulation
- 7. Pump cement, filling 7" annulus and leaving 7" casing full of cement. Use 216 sacks of Class H, 60/40 poz cement with 6% gel. Mix cement at 13.2 ppg with a yield of 1.53 cu. ft. per sack.
- 8. Cut casing strings 5 ft below ground level.
- 9. Weld on steel cap with lease identification.

RECEIVED


ANSAS COPPORATION COMMISSION

10. Restore location.

FEB 2 5 2002


CONSERVATION DIVISION

Kinsler B 1
Section 08, T32S, R40W
Chase Gas Field
Morton County, Kansas



Not to scale

Kinsler B 1
Section 08, T32S, R40W
Chase Gas Field
Morton County, Kansas



Not to scale

Missing Log
Kinsler B 1 – Abandonment
Section 08, T32S, R40W
Morton County

We have searched the log files in both Ulysses, Kansas and Houston, Texas and cannot find a copy of any log run in this well.

LUNNSAS C - ATION COMMISSION

FEB 25 2002

CONSERVATION DIVISION