

Conservation Division
266 N. Main St., Ste. 220
Wichita, KS 67202-1513



Phone: 316-337-6200
Fax: 316-337-6211
<http://kcc.ks.gov/>

Shari Feist Albrecht, Chair
Jay Scott Emler, Commissioner
Pat Apple, Commissioner

Sam Brownback, Governor

April 6, 2015

Murfin Drilling Company, Inc.
1040 Plains Ave
PO Box 661
Colby, KS 67701

Re: Heier-Racette 1-34
SE/4 Sec. 34-12S-33W
Logan County, Kansas
15-109-21257-00-00

Dear Sir or Madam:

This letter is to inform you that you have been granted an extension of time in which to close the drilling pits associated with the Heier-Racette 1-34 well.

The original 365 days for closure expired on 03/05/2015. This extension will expire on 7/05/2015. We urge you to make every effort to close these pits within this time frame. In the event there is water standing in these pits, please dewater and dispose of fluids in an authorized disposal facility to expedite closure. Extension of this time frame automatically extends the time period for filing the closure of surface pit form, **but not the time period for filing the waste transfer form (CDP-5).**

*Failure to close the pit or request an additional extension prior to the expiration date shall result in a monetary penalty in accordance with K.A.R. 82-3-602(a). An additional pit extension may be renewed upon request, but **no pit permit extension shall be extended beyond six months after the original deadline.***

Please complete the pit closure form (CDP-4) through Kolar (Kansas On-Line Automated Reporting) at <https://kolar.kgs.ku.edu>.

If you have any questions in this regard, please do not hesitate to contact Kathy Haynes at (316) 337-6243.

Sincerely,

Ryan A. Hoffman
Director

Cc: File
District



**MURFIN DRILLING
COMPANY INC.**

Colby District
1040 Plains Ave, PO Box 661
Colby, KS 67701
Phone: 785-462-6781

March 27, 2015

Sammy Flaharty
Kansas Corporation Commission
266 N Main, Ste 220
Wichita, KS 67202-1513

Sammy,

We are asking for an extension on the following well due to wet conditions at the pit site. Pits are still too wet to backfill. A 90 day extension should be long enough.

<u>API #</u>	<u>Well Name</u>	<u>Location</u>	<u>County</u>	<u>Spud date</u>
15109212570000	Heier Racette #1-34	34-12S-33W	Logan	3/5/14

Sincerely,

John Turner

John Turner
Production Superintendent
Murfin Drilling Company, Inc

JT/ar

Received
KANSAS CORPORATION COMMISSION

APR 02 2015

CONSERVATION DIVISION
WICHITA, KS

4-2-15